



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

19/7/2023

Survey Details:

| | |
|---------------------|-------------------------|
| Date of loss | 13-May-23 |
| Date of appointment | 23-May-23 |
| Date of survey | 26-May-23 |
| Location of survey | BISADO TECHNOLOGIES LLP |

Vehicle Details:

| | |
|----------------------|-------------------------|
| Claim Type: | Third Party Claim |
| Vehicle number | FBU 7664D |
| Make and Model | YAMAHA XMAX 300 ABS CVT |
| Date of registration | 6/3/2023 |
| Excess | - |
| Market Value | \$ 23,000.00 |
| Parf Rebate | \$ 11,168.00 |
| Nett Loss | \$ 11,832.00 |

Repair details:

| | |
|------------------|------|
| Initial Estimate | \$ - |
|------------------|------|

Proposed/Revised repair cost:

| | |
|--------------------------------|------|
| Parts | |
| Check items (estimate) | |
| Labour | |
| Total | \$ - |
| Lump Sum(if applicable) | |

| | |
|----------------------------------|----------|
| Number of days for repair | 3 |
|----------------------------------|----------|



Remarks:

The estimate repair cost of the damaged vehicle is in the region of \$2,000.00 - \$3,000.00.

Mandate:

| Liability(TP) | % | |
|-----------------------|----------------|-------------|
| Proposed repair cost | \$ | |
| Loss of use | \$ | no. of days |
| Loss of rental | \$ | no. of days |
| Loss of income | \$ | no. of days |
| LTA search fees | \$ | |
| Others | \$ | |
| Proposed Total | #VALUE! | |