

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Vehicle number: JSE6680

Make & Model: Toyota Camry

Chassis number: PN153DK5100003515

No.	Description of spare parts	Qty	Amount S\$
1	Bootlid	1	\$ <i>bt</i> 913.00
2	Bootlid centre emblem	1	\$ <i>net</i> 86.00
3	Bootlid "Camry" emblem	1	\$ <i>net</i> 65.00
4	Bootlid "2.0" emblem	1	\$ <i>net</i> 56.00
5	Bootlid "X" emblem	1	\$ <i>net</i> 41.00
6	Bootlid "D-45" emblem	1	\$ <i>net</i> 58.00
7	Bootlid centre chrome	1	\$ <i>live</i> 263.00
8	Bootlid RH lamp	1	\$ <i>cur</i> 489.00
9	Bootlid RH lamp upper chome	1	\$ <i>cur</i> 174.00
10	Bootlid LH lamp	1	\$ <i>x</i> 489.00
11	Bootlid LH lamp upper chome	1	\$ <i>x</i> 174.00
12	Bootlid lock	1	\$ <i>bt</i> 428.00
13	Bootlid lock catch	1	\$ <i>x</i> 79.00
14	Bootlid inner trim	1	\$ <i>fn</i> 298.00
15	Bootlid inner trim clips	1set	\$ <i>20w</i> 80.00
16	Bootlid weatherstrip	1	\$ <i>cut</i> 218.00
17	Bootlid RH hinge	1	\$ <i>x</i> 129.00
18	Bootlid LH hinge	1	\$ <i>x</i> 129.00
19	Rear bumper	1	\$ <i>de</i> 687.00
20	Rear bumper clips	1set	\$ <i>30w</i> 80.00
21	Rear bumper RH side retainer	1	\$ <i>x</i> 76.00
22	Rear bumper LH side retainer	1	\$ <i>x</i> 76.00
23	Rear bumper reinforcement	1	\$ <i>bt</i> 598.00
24	End panel	1	\$ <i>bt</i> 657.00
25	End panel inner garnish	1	\$ <i>de</i> 326.00
26	End panel inner garnish clips	1set	\$ <i>20w</i> 70.00
27	RH taillamp assy	1	\$ <i>cur</i> 598.00
28	RH taillamp panel	1	\$ <i>x</i> 154.00
29	RH taillamp lock clips	1set	\$ <i>x</i> 50.00
30	RH taillamp lower bracket	1	\$ <i>x</i> 46.00
31	LH taillamp assy	1	\$ <i>cur</i> 598.00
32	LH taillamp panel	1	\$ <i>x</i> 154.00
33	LH taillamp lock clips	1set	\$ <i>x</i> 50.00
34	LH taillamp lower bracket	1	\$ <i>x</i> 46.00
35	Rear RH fender inner trim cover	1	\$ <i>fn</i> 427.00

36	Rear RH fender inner trim cover clips	1set	\$ X	80.00
37	Rear LH fender inner trim cover	1	\$ 427	427.00
38	Rear LH fender inner trim cover clips	1set	\$ X	80.00
39	Rear compartment panel upper cover	1	\$ X	298.00
40	Rear compartment panel RH sponge tools tray	1	\$ 109	109.00
41	Rear compartment panel LH sponge tools tray	1	\$ 109	109.00
42	Exhaust silencer	1	\$ X	983.00
43	Exhaust silencer gasket	1	\$ X	58.00

\$ 11,006.00
 Parts less 25% \$ 2,751.50
 Total: \$ 8,254.50

No.	Special Nett Items	Qty	Amount S\$
1	Bootlid reverse camera	1	\$ X 750.00
2	Rear bumper lower spoiler	1	\$ 600 1,200.00
3	Rear bumper lower spoiler RH reflector	1	\$ X 178.00
4	Rear bumper lower spoiler LH reflector	1	\$ X 178.00
5	End panel joint sealant	1	\$ X 80.00

Total: \$ 2,386.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 700 1,500.00
2	Spray painting on affected areas and panels	\$ 700 1,300.00
3	Check wiring and lighting system on affected areas	\$ 30 80.00
4	Apply rust coating chemical on affected areas and panels	\$ 30 80.00
5	Remove and replace bootlid reverse camera to assist repair	\$ 30 120.00
6	Remove and replace bootlid inner parts to new bootlid	\$ 60 120.00
7	Remove and replace rear bumper reverse sensors to assist repair	\$ 30 100.00
8	Remove and replace exhaust silencer and gasket to assist repair	\$ X 180.00

Remove and replace rear inner trims, sponge tool tray and boards to assist repair	\$ 60 380.00

Agreed Amount: _____ (Part by Part / Lump sum)
 Working days: _____

Total: \$ 2,360.00

Spare Parts: \$ 8,254.50
 Special Nett: \$ 2,386.00
 Labour: \$ 2,360.00

Total Amount: \$ 13,000.50

Taufiq 97495749
 up 24/5/23 & 12pm
 4/5 Resurvey after repair
 Taufiq Chhanta w
 6 days
 - To check consistency of accident
 - To check part prices

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance

Acknowledged by:

Signature:

Date: