



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: RODERIC YUEN

Ref: CS/INC23005218/Uqp3e2

Date: 07/06/2023

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 1525X	Veh. Inspected	SNH 264Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1223049-002	Excess (\$)	0.00
Assign From	HAZALYSA BIN IBRAHIM	Assign Date	23/05/2023

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	RV31008334	Colour	WHITE
Odometer	13894 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	8 mm
L/H Front Tyre	215/60 R16	DUNLOP	8 mm
R/H Rear Tyre	215/60 R16	DUNLOP	8 mm
L/H Rear Tyre	215/60 R16	DUNLOP	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/05/2023	Inspect Date / Time	23/05/2023 (02:13 PM)
Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**