

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

22-May-23

ESTIMATE REPAIR BILL FOR NIRO PLUS REGN NO: SHD 1681 L

1 pc	Rear bumper Upper	\$	535.00	By
1 pc	Rear bumper lower	\$	554.00	cut
1 pc	Rear bumper o/s moulding	\$	15.00	cut
1 pc	Rear o/s fender garnish	\$	144.00	cut
1 pc	Rear o/s fender inner shield	\$	255.00	X
1 pc	Rear bumper o/s reflector	\$	178.00	X un
1 pc	Rear bumper o/s reflector cover	\$	43.00	X
2 pcs	Rear bumper side bracket n/s & o/s @\$25.00	n/sx \$	50.00	o/s X un
1 pc	Rear o/s door	\$	1,542.00	Rx
1 pc	Rear o/s rim	\$	956.00	cut
		\$	4,272.00	1669
	Less 10%	\$	427.20	
		\$	3,844.80	1502.10

S/NETT

1 set	Rear bumper clips	\$	58.00	300
1 set	Rear o/s fender inner shield clips	\$	58.00	x un
1 pc	Rear o/s fender sticker	\$	60.00	un 90
	Sundry	\$	50.00	X un
	Check wheel alignment	\$	50.00	✓
	To dismantle and refit reverse sensor into new bumper	\$	120.00	30
	To dismantle and refit rear o/s door inner component into new shell door	\$	150.00	60
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the rear o/s fender etc	\$	650.00	500
	To putty and spray painting on the rear bumper upper, rear bumper lower, rear o/s fender, rear o/s door	\$	900.00	600
	To apply rustproofing on the repaired and replaced panels	\$	150.00	30
	Total	\$	6,090.80	1270

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

Tanfong 97495749 WP 24/5/23 @ 2300
 P/P Resurvey new parts 04 days
 tanfong @ lkk auto.com 04 days #

1502.10
 90
 1270
 \$2862.10