



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: YEE PEI LI

Ref: CS/INC23005221/Anp3e2

Date: 13/07/2023

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFM 1630K	Veh. Inspected	SJN 3621X
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1224160-001	Excess (\$)	0.00
Assign From	HAZALYSA BIN IBRAHIM	Assign Date	23/05/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PICNIC	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JTEGH23BX00026343	Colour	SILVER
Odometer	261118 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DAVANTI	6 mm
L/H Front Tyre	215/60 R16	DAVANTI	6 mm
R/H Rear Tyre	215/60 R16	DAVANTI	6 mm
L/H Rear Tyre	215/60 R16	DAVANTI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/05/2023	Inspect Date / Time	23/05/2023 (03:08 PM)
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	11 Working Days
--	------------------------