



**Letter of Claims**  
**Request of direct settlement.**

We are submitting a claim on behalf of our customer Cindy Loh Yoke Fun.  
NRIC 7941D. insured of vehicle SMU 8816X against  
your insured vehicle number SLX5577B. (China Topix.)  
On the accident dated on 14/5/2023 (ddmmyyyy) along  
Bukit Timah Rd.

Dated this 23 (day) of 5 (month) 20 23.

Volkswagen Group Singapore  
247 Alexandra Road  
Singapore 159934  
DID: 63057217/63057299  
HP: 93867833  
[shushi.tang@vw.com.sg](mailto:shushi.tang@vw.com.sg)

# VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation Non binding - Preview

Page 1/2

Document no.  
Document date 23-05-2023  
Customer no. 5211001170  
Customer GST-ID 200208384E  
Dealer 30001  
Job order number 2023013720/ 1  
Job order date 22-05-2023  
Service Advisor SHU SHI TANG

Company  
CHINA TAIPING INSURANCE (S) PL  
3 ANSON ROAD  
#18-00 SPRINGLEAF TOWER  
Singapore 079909

Customer Details:  
Ms.  
CINDY  
LOH YOKE FUN  
7 PINE GROVE  
#11-04  
SINGAPORE 597592

License plate SMU8816X	Model code 5T13NZC1	First registration 01-09-2020	VIN WVGZZZ1TZKW072374	Model Touran Comfortline EQP 1.4 TSI 110kW DSG	Mileage 22,927
---------------------------	------------------------	----------------------------------	--------------------------	--	-------------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#6	280.00	302.40
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	480.00	518.40
5TA853630A DPJ	Vw Sign Black/Bright Chro	1	pcs.	122.53	#6	122.53	132.33
5TA853687 2ZZ	Inscription Bright Chrome NAME PLATE - TOURAN	1	pcs.	96.80	#6	96.80	104.54
5TA807417 GRU	Cover For Bumper Primed	1	pcs.	1,307.91	#6	1,307.91	1,412.54
5TA807568A 9B9	Spoiler Satin Black	1	pcs.	399.17	#6	399.17	431.10
5TA807305	Bumper REINFORCEMENT	1	pcs.	766.55	#6	766.55	827.87
5TA807863	Attachment Strip BUMPER CTR BRACKET	1	pcs.	80.40	#6	80.40	86.83
5TA807453	Guide Piece LHR BUMPER BRACKET ( UPPER )	1	pcs.	58.20	#6	58.20	62.86
5TA807454	Guide Piece RHR BUMPER BRACKET ( UPPER )	1	pcs.	58.20	#6	58.20	62.86
5TA807393	Guide Piece LHR BUMPER BRACKET ( SIDE )	1	pcs.	56.51	#6	56.51	61.03
5TA807394	Guide Piece RHR BUMPER BRACKET ( SIDE )	1	pcs.	56.51	#6	56.51	61.03
	LABOUR	3	pcs.	840.00	#6	2,520.00	2,721.60
	SPRAY PAINT	3	pcs.	800.00	#6	2,400.00	2,592.00
	REVERSE SENSOR	1	pcs.	400.00	#6	400.00	432.00
	CHINA TAIPING DIRECT DOA: 19/5/2023 TP VEH: SLX5577B SURVEY BY:						

Quotation valid till 29-05-2023

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#6	760.00	8,322.78	8%	726.62	9,082.78	9,809.40
<b>Total</b>	<b>760.00</b>	<b>8,322.78</b>		<b>726.62</b>	<b>9,082.78</b>	<b>9,809.40</b>

Customer

Service Advisor

# VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



SKODA

Commercial  
Vehicles

## Quotation

Non binding - Preview

Page 2/2

Company  
CHINA TAIPING INSURANCE (S) PL  
3 ANSON ROAD  
#18-00 SPRINGLEAF TOWER  
Singapore 079909

Customer Details:  
Ms.  
CINDY  
LOH YOKE FUN  
7 PINE GROVE  
#11-04  
SINGAPORE 597592

Document no.  
Document date 23-05-2023  
Customer no. 5211001170  
Customer GST-ID 200208384E  
Dealer 30001  
Job order number 2023013720/ 1  
Job order date 22-05-2023  
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SMU8816X	5T13NZC1	01-09-2020	WVGZZZ1TZKW072374	Touran Comfortline EQP 1.4 TSI 110kW DSG	22,927

-----VISIT OUR WEBSITE: [aftersales.vw.com.sg](https://aftersales.vw.com.sg) (for online service appointments) and [volkswagen.com.sg](https://volkswagen.com.sg) and [www.skoda.com.sg](https://www.skoda.com.sg) (for additional services, products and promotions).-----

All invoices are denominated in SGD, unless otherwise stated.