



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23005239/Uvp3m4 Date: 06/06/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GW 9733E	Veh. Inspected	SJR 7949D
	Policy No.		Coverage (\$)	0.00
	Claim No.	BVS23/0333	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	23/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PICNIC (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	JTEGH23B100026795	Colour	BLACK
	Odometer	192644 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60R16	FIRESTONE	6 mm
	L/H Front Tyre	215/60R16	FIRESTONE	6 mm
	R/H Rear Tyre	215/60R16	FIRESTONE	6 mm
	L/H Rear Tyre	215/60R16	FIRESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	12/05/2023	Inspection Date	24/05/2023
	Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		
5a. Remarks				
	A)REGISTRATION DATE: 14 JUL 2009 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	