

COMFORTDELGRO ENGINEERING PTE LTD.

REPAIR ESTIMATE*

VEHICLE NO SHA4024E
 MAKE REG. 13.12.2017
 MODEL HYU- I40

09.04.2023

CHIANG/ INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER BRACKET SIDE RH ? X MV		\$35.60	\$35.60
10	REAR BUMPER CLIPS X MV		\$2.20	\$22.00
1	REAR BUMPER SCR -			\$553.00
1	REAR BUMPER UNDER COVER ? X MV			\$228.00
1	REAR BUMPER REFLECTOR RH ? X MV			\$32.00
				\$870.60
				\$174.12
				\$696.48 442.40
				20.00% DISCOUNTED TOTAL
1	REAR BUMPER MAT MEL			\$50.00
1	REVERSE SENSOR X mn			\$135.70
				\$217.13
	Labour Charge			\$450.00 280
	Panel Beating			\$300.00 250
	Spray Painting Charge			\$60.00 30
	Remove/refix reverse sensor			\$60.00 X MV
	Tuff Kote			\$870.00
	TOTAL LABOUR			
	ESTIMATE TOTAL		1052.40	\$1,786.61
			210.48	

Exact

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

= 841.92 2 days
 ≈ 850/m 4/9
 13141B
 J 12/20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: