



**COMFORTDELGRO ENGINEERING PTE LTD.**

**REPAIR ESTIMATE\***

VEHICLE NO **SHA4024E**

09.04.2023

MAKE **REG. 13.12.2017**

MODEL **HYU- I40**

**CHIANG/ INCOME**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER BRACKET SIDE RH ?		\$35.60	\$35.60
10	REAR BUMPER CLIPS*		\$2.20	\$22.00
1	REAR BUMPER <i>scr</i>			\$553.00
1	REAR BUMPER UNDER COVER ?			\$228.00
1	REAR BUMPER REFLECTOR RH ?			\$32.00
				<b>\$870.60</b>
				20.00% <b>DISCOUNTED TOTAL</b>
				\$174.12
				<b>\$696.48</b>
1	REAR BUMPER MAT <i>mel</i>			\$50.00
1	REVERSE SENSOR X			\$135.70
				<b>\$217.13</b>
	<b>Labour Charge</b>			
	Panel Beating			\$450.00
	Spray Painting Charge			\$300.00
	Remove/refix reverse sensor			\$60.00
	Tuff Kote			\$60.00
	<b>TOTAL LABOUR</b>			<b>\$870.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$1,786.61</b>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

*280*  
*250*  
*30*  
*XMMU*

*15/04*

**TAKE PHOTOGRAPH  
BEFORE / AFTER  
SPRAY PAINTING**

*2 days*

*4/9*

*13141B 5pm*

*[Signature]*