



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23005243/Avp3e2 Date: 30/05/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 531D	Veh. Inspected	SMS 3950J	
Policy No.		Coverage (\$)	0.00	
Claim No.	IVS23/0929	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	23/05/2023	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 216D	c.c	1496	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	WBA2B32050V791367	Colour	WHITE	
Odometer	72273 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	205/55 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/55 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/55 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/04/2023	Inspection Date	23/05/2023	
Survey held at	9 PULASAN ROAD			
Repairer	KANG CAR REPAIRERS PTE LTD			
5a. Remarks				
A)REGISTRATION DATE: 30 AUG 2016 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	