

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : LIBERTY INSURANCE PTE LTD
51 CLUB STREET
#03-00 LIBERTY HOUSE
SINGAPORE 069428

TEL: 62218611

FAX: 62241047

ATTN: Motor Claim Department

Claim Type: Third Party

Accident Date: 25/04/2023

Estimate No: EST2300195

Date: 16 May 2023

Veh Reg No: SMS3950J

Make/Model: BMW 216D ACTIVE
TOURER D/AB LED

Chasis No: WBA2B32050V791367

Reg. Date: 30/08/2016

Your Ref No: YP531D

Estimate Repair Cost to Vehicle No :SMS3950J

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	List Price		
1	1 PC BONNET <i>Dented.</i>	1,889.70	✓
2	1 PC HEADLAMP LH <i>crack</i>	2,789.60	✓
3	1 PC FRT BUMPER <i>Repair</i>	1,329.30	+
4	1 PC FRT BUMPER RETAINER <i>new</i>	102.30	+
5	1 PC FRT PARKING SENSORS <i>new</i>	284.90	+
		6,395.80	
	Less 10%	639.58	5,756.22
	Labour		
6	1 TO CHECK WIRING	80.00	30
7	1 TO SPRAY PAINTING DAMAGED PORTION, INCLUDING SUPPLY OF PAINT MATERIALS SUCH AS MASKING TAPE, SAND PAPERS, PRIMER, POLISHING COMPOUND AND CHEMICAL ETC.	900.00	500
8	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	750.00	400
9	1 PROGRAMME AND SETTING	350.00	x.
		2,080.00	2,080.00

check

11 May

Liability

930

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : LIBERTY INSURANCE PTE LTD
51 CLUB STREET
#03-00 LIBERTY HOUSE
SINGAPORE 069428
TEL: 62218611 FAX: 62241047
ATTN: Motor Claim Department

Estimate No: **EST2300195**
Date: 16 May 2023

Veh Reg No: **SMS3950J**
Make/Model: BMW 216D ACTIVE
TOURER D/AB LED
Chasis No: WBA2B32050V791367
Reg. Date: 30/08/2016
Your Ref No: YP531D

Claim Type: Third Party
Accident Date: 25/04/2023

Estimate Repair Cost to Vehicle No :SMS3950J

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Total		S\$ 7,836.22
	Add GST @ 8%		626.90
	Total Amount Payable		<u>S\$ 8,463.12</u>

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND FOUR HUNDRED SIXTY THREE AND CENTS
TWELVE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time
which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--

Adrian Lj
4/5 23/05/23.
04 Days.
total: 5141.37
4/5 4.11C.