

ASS REC. BY: Wef

REF:

CC4/LPC23005245/Rpa3

856f

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMK 9959M

at Workshop m/s KAH MOTOR

of 255, ALEXANDRA RD

Insured: LPC

Policy No:

Claims No:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 77k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SMK 9959M

Yr Regn: 2019 / Mgy

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA JAZZ 1.3 CVT c.c 1318

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 053977 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JH MKK 3850KS214 489

Gen. Cond: Good / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRIM / STD A/Rim or

Tyre Size: F: 175/65R15

R:

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 20/05/23 D.O.I. 24/05/23

Survey held at: KAH MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 56K

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555

Registration No : SMK9959M

Chassis No : JHMGK3850KS214489

Model : JAZZ 1.3LXR CVT 19YM (EURO 6)

Owner's Name : LOW WAI FONG

Ins Policy No. :

Date of Accident : 20/5/2023

Document No. : SQT23001566 **Page** 1

Date : 22. May 2023

Customer No. : WZL009

Svc Advisor :

Engine No : L13B14101264

Date | Time : 22. May 2023 7:05:27 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
04715-T5A-J50ZZ	FACE,RR.BUMPER <i>de</i>	1	496.90	25	372.67	29.81	402.48
71505-T5A-J50	GARNISH,RR.BUMPER <i>X</i>	1	41.00	25	30.75	2.46	33.21
71502-T5A-J60	COVER,R.RR.BUMPER <i>?</i>	1	22.10	25	16.57	1.33	17.90
71507-T5A-J60	COVER,L.RR.BUMPER <i>?</i>	1	22.10	25	16.57	1.33	17.90
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE <i>re</i>	1	18.10	25	13.57	1.09	14.66
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE <i>re</i>	1	18.10	25	13.57	1.09	14.66
91505-TM8-003	CLIP,BUMPER <i>re</i>	7	2.30	25	12.07	0.97	13.04
68100-T5A-U10ZZ	TAIL GATE COMP <i>re</i>	1	782.10	25	586.57	46.93	633.50
74440-T5A-003	WEATHERSTRIPTAILGATE <i>X</i>	1	92.30	25	69.22	5.54	74.76
74801-T5S-K01	LOCK ASSY,TAILGATE <i>X</i>	1	91.10	25	68.32	5.47	73.79
66100-TAR-T00ZZ	PANEL COMPRR. <i>X</i>	1	342.90	25	257.17	20.57	277.74
84640-T5A-003ZA	LINING ASSY,RR.PANEL <i>X</i>	1	60.80	25	45.60	3.65	49.25
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER <i>X</i>	1	61.90	25	46.42	3.71	50.13
74890-T5A-A11	GARNISH ASSY,RR LICENCE <i>X</i>	1	112.90	25	84.67	6.77	91.44
75701-T5A-000	EMBLEM <i>re</i>	1	10.70	25	8.02	0.64	8.66
90301-ST0-003	NUT,PUSH 3MM <i>re</i>	2	2.10	25	3.15	0.25	3.40
33500-T5A-J02	TAILLIGHT ASSY,R. <i>X</i>	1	258.40	25	193.80	15.50	209.30
33550-T5A-J02	TAILLIGHT ASSYL. <i>X</i>	1	258.40	25	193.80	15.50	209.30
34150-T5A-J01	LIGHT ASSYR.LID <i>X</i>	1	94.20	25	70.65	5.65	76.30

Printed on 22/5/2023 7:10:15 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SMK9959M
Chassis No : JHMGK3850KS214489
Model : JAZZ 1.3LXR CVT 19YM (EURO 6)
Owner's Name : LOW WAI FONG
Ins Policy No. :
Date of Accident : 20/5/2023

Document No. : SQT23001566
Date : 22. May 2023
Customer No. : WZL009
Svc Advisor :
Engine No : L13B14101264
Date | Time : 22. May 2023 7:05:27 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
34155-T5A-J01	LIGHT ASSYL.LID X	1	94.20	25	70.65	5.65	76.30
73211-T5A-J01	GLASS SETRR.WINDSHIELD X	1	625.60	25	469.20	37.54	506.74
73127-TY0-000	RUBBER CWINDSHIELD DAMPER X	1	12.30	25	9.22	0.74	9.96
73214-T5A-013	RUBBERWINDSHIELD DAMPER X	2	7.60	25	11.40	0.91	12.31
73226-SZW-000	DAMPERSTD 5X5 X	1	9.10	25	6.82	0.55	7.37
BO-WS-SEALANT	WINDSCREEN SEALANT (N) X	1	60.00		60.00	4.80	64.80
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR ?	1	320.00		320.00	25.60	345.60
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) X	1	45.00		45.00	3.60	48.60
Sum Item					3095.45	247.65	3,343.10
BOSUN	SUNDRIES	1	110.00	30	110.00	8.80	118.80
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	250.00	150	250.00	20.00	270.00
BOJSE	BODY JOINT SEALANT.	1	120.00	X	120.00	9.60	129.60
BOBC	BODY UNDERSIDE COATING (N)	1	520.00	X	520.00	41.60	561.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	520.00	X	520.00	41.60	561.60
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	250.00	180	250.00	20.00	270.00
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	650.00	580	650.00	52.00	702.00
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	650.00	X	650.00	52.00	702.00
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00	X	650.00	52.00	702.00
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00	X	650.00	52.00	702.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00	X	650.00	52.00	702.00
BKRP21M	CUT OFF & RENEW RR PANEL. STRAIGHTEN RR FENDERS AN	1	5000.00	1950	5000.00	400.00	5400.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3200.00	1560	3200.00	256.00	3456.00
Sum Labor					13220.00	1,057.60	14,277.60

Survey By

Printed on 22/5/2023 7:10:15 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SMK9959M
Chassis No : JHMGK3850KS214489
Model : JAZZ 1.3LXR CVT 19YM (EURO 6)
Owner's Name : LOW WAI FONG
Ins Policy No. :
Date of Accident : 20/5/2023

Document No. : SQT23001566 Page 3
Date : 22. May 2023
Customer No. : WZL009
Svc Advisor :
Engine No : L13B14101264
Date | Time : 22. May 2023 7:05:27 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST	
Date & Time	24/05/23 @ 1405				Total Amount	16,315.45	1,305.25	17,620.70
Excess					Total (Inclusive of GST)			17,620.70

Status : 6 days
Signature :

Reserve - 4890014058
Reg 54 part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 22/5/2023 7:10:15 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	856F
Vehicle No.:	SMK9959M
Vehicle to be Exported:	No
Intended Deregistration Date:	24 May 2023
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.3 CVT
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	L13B14101264
Chassis No.:	JHMGK3850KS214489
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$15,682.00
Original Registration Date:	13 May 2019
First Registration Date:	13 May 2019
Transfer Count:	0
Actual ARF Paid:	\$5,682.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 May 2029
PARF Rebate Amount:	\$4,261.00
COE Expiry Date:	12 May 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,659.00
COE Rebate Amount:	\$15,903.00
Total Rebate Amount:	\$20,164.00

The information contained herein is correct as at 24 May 2023

OK

Honda Jazz 1.3A

\$77,800 Instalment \$892/mth

Shortlist

Get Warranty

Loan Calculator

TRENDING NOW

 Nissan QashQai 2014 Part 2

Overview

Financial

Photo

Research

Depreciation	\$12,450 / year
Reg. Date	31-May-2019 (6yrs 5days COE left)
Manufactured	2019
Mileage	64,000 km (16.1k / year)
Transmission	Auto
Engine Cap	1,318 cc
Road Tax	\$578 / year
Power	73.0 kW (97 bhp) View specs of the Honda Jazz (2014-2021)
Curb Weight	1,052 kg
COE	\$36,704
OMV	\$15,621
ARF	\$5,621
Dereg Value	\$26,309 as of today
No. of Owners	1