



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : HSBC LIFE (SINGAPORE) PTE LTD

DATE: 26/5/2023

### Survey details

Date of loss	20/5/2023
Date of appointment	24/5/2023
Date of survey	25/5/2023
Location of survey	CCK CAR RENTAL

### Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle number	FBN 9620D
Make and Model	YAMAHA YZF-R155
Date of registration	11/1/2019
Excess	
Market Value	\$10,000.00
Parf Rebate	\$2,031.00
Nett Loss	\$7,969.00

### Repair details

Initial Estimate	
------------------	--

### Proposed/Revised repair cost:

Parts	
"Check items (Estimated)	
Labour	
Total	
Lump Sum (Estimated)	
Number of days of repair	6 days (est)

### **Remarks:**

Daamges Consistent

The vehicle sustained damaged at the n/s body and rear o/s portion.

The estimated repair cost of the damaged vehicle is in the region of \$4,000.00-\$5,000.00