

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT HSBC LIFE (SINGAPORE) PTE LTD Ref: CS3/HSB23005246/Tvp3m4 10 MARINA BOULEVARD #48-01 MARINA BAY Date: 30/05/2023 FINANCIAL CENTRE TOWER 2 SINGAPORE ATTN: CYNTHIA LOH Code: HSB Policy Particulars :- (THIRD PARTY CLAIM) 1. **SHA 8716R** FBN 9620D Insured Veh. Veh. Inspected 0.00 Policy No. Coverage (\$) S3M04MRG 0.00 Claim No. Excess (\$) CYNTHIA LOH 24/05/2023 **Assign Date** Assign From 2. **Vehicle Particulars & Condition** YAMAHA YZF-R155 155 Make & Model C.C **HIDDEN** Engine No. Year of Reg. 2019 MH3RG4710KK093709 **BLACK** Chassis No. Colour Odometer IN ORDER Steering **IN ORDER** NIL Modification **Brakes** GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 110/70 R17 **MAXXIS** 5 mm L/H Front Tyre mm 140/70 R17 **MAXXIS** R/H Rear Tyre 5 mm L/H Rear Tyre mm **Description of Damages** 4. THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND REAR O/S PORTION. 5. **General Information** 20/05/2023 **Inspect Date / Time** 25/05/2023 (02:00 PM) **Accident Date** 1102 SERANGOON ROAD SINGAPORE 328196 Survey held at **CCK CAR RENTAL** Repairer 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

Report Ref No. CS3/HSB23005246/Tvp3m4

Estimate Days of Repair

Inspected By

5b.

MOHAMAD TAUFIKH

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

6 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.