



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

HSBC LIFE (SINGAPORE) PTE LTD

INV No. AC2303867

10 MARINA BOULEVARD #48-01 MARINA BAY

INV Date 16/06/2023

FINANCIAL CENTRE TOWER 2

Reference CS3/HSB23005247/Avp3m4

SINGAPORE 018983

Code HSB

ATTN: GARNET LOW

PROFESSIONAL SERVICE FEE

Vehicle No. SME 4360D

Insured Veh. SHA 1689G

Claim No. S3M04MQ2

Policy No. VFX/P2419138

Accident Date 19/05/2023

Inspection Date 05/06/2023

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 06.06.2023)	
Repaired vehicle before return to claimant as per NIMA Protocol (Photo taking + Transport on 12.06.2023)	
Subtotal	100.00
GST (8%)	8.00
Grand Total	108.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

SML