



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SINGAPORE CIVIL DEFENCE FORCE (MHA05)

Ref: CS/SCD23005256/Tvp3

91 UBI AVE 4
SINGAPORE 408827
SINGAPORE 408827

Date: 24/05/2023

Code: SCD

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	XE 5178C
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	22/05/2023

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	Inspection Date	24/05/2023
Survey held at	FIRE STATION PAYA LEBAR FIRE STATION 91, UBI AVE 4, SP 408827	

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.