

SCOPE OF WORK

- 1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

VEHICLE TYPE	PL	REGISTRATION NO	XE 5178 C	REPAIR TYPE	ACCIDENT
MAKE/MODEL	SCANIA	UNIT	STN 21	CONTRACTOR	INDECO

S/N	ITEM DESCRIPTION	PARTS					LABOUR		
		PARTS QTY	PARTS COST PER UNIT (\$)	MARK UP RATE	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	MAN-HOUR RATE (\$)	MAN-HOUR QTY	TOTAL MAN-HOUR COST (\$)
	SCOPE OF REPAIRS								
A	Labour								
1	To Dismantle Entire LH Side Compartment for Damage Repairs						\$61.80	20	\$1,236.00
2	To Dismantle Locker 1 Slider Track for Damage Repairs						\$61.80	15	\$927.00
3	To Dismantle No 1 Roller Shutter for Damage Repairs						\$61.80	4	\$247.20
4	To Cut & Weld Locker 1 Pillar						\$61.80	40	\$2,472.00
5	To Cut & Weld Locker 1 Front Body Bottom Frame						\$61.80	48	\$2,966.40
6	To Cut & Weld Angle Support for Bottom Frame						\$61.80	35	\$2,163.00
7	To Cut & Weld Damage LH Rear Mudguard Step						\$61.80	35	\$2,163.00
8	To Replace Damage Swing Down Support Brackets						\$61.80	28	\$1,730.40
9	To Replace Damage Shelf Support Base & Support Brackets						\$61.80	20	\$1,236.00
10	To Realign & Panel Beat Rear LH Wheel Arch						\$61.80	18	\$1,112.40
11	To Putty & Spary Paint Damage Rear LH Wheel Arch						\$61.80	10	\$618.00
12	To Replace Damage No 1 Roller Shutter						\$61.80	4	\$247.20
							SUB TOTAL	277	\$17,118.60