

(00/10)

wef

ASS. REC. BY: John

REF:

CS/FC/23005266/RVP3

6014

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: SBS 1104at Workshop m/s Eurokarsof 27A, Tanjong Pagar Road

Insured:

PC12

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

11.30

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

101K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SBS 1104

Yr Regn:

2019 / July

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

MAZDA 6 2.0 AT EXECUTIVE 1998

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

72513

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM 64L1072KO312838

Gen. Cond: ☒ Good / ☒ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

225/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

15/05/23

D.O.I.

29/05/23

Survey held at

TRANSURKARS

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 60K

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS. SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

Time & Address:
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877
 motor_claims@first-insurance.com.sg
 Email/Fax No

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Contact No:
 Acknowledged by Repairer
 Signature:
 Date:

Type of Claim
 THIRD PARTY

Vehicle No:
 SBB110G
 Brand & Model:
 MAZDA 6
 Chassis/VIN No:
 JM6GL1072K0312838
 Date Of Registration:
 19/07/2019

REPAIR ESTIMATE
 Date:
 19-May-23
 Franchise:
 MAZDA
 Contact Person (Eurokars)/Wip No:
 WONG/58460
 Contact No (Eurokars):
 6331 0680

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	REAR BUMPER GL3 (REAR BUMPER) <i>de</i>	MGSK2-50-221ABB	1		-	\$ 1,260.75
2	FASTENER <i>na</i>	MB45A-56-146A	6		-	\$ 14.16
3	GROMMET, SCREW <i>na</i>	MBHN1-50-021A	4		-	\$ 9.44
4	NUT, CLIP <i>na</i>	MC274-50-133	4		-	\$ 9.44
5	RETAINER LHR BUMPE GJ (REAR BUMPER RETAINER LH) ?	MGJR9-50-2J1	1		-	\$ 41.73
6	RETAINER RHR BUMPER GJ (REAR BUMPER RETAINER RH) ?	MGJR9-50-2H1	1		-	\$ 41.73
7	COVER(L), TOWING HOOK GL3 (REAR TOWING COVER LH) <i>na</i>	MGSH7-50-EL1 BB	1		-	\$ 56.22
8	COVER(R), TOWING HOOK GL3 (REAR TOWING COVER RH) X	MGSH7-50-EK1 BB	1		-	\$ 56.22
9	REFLECTOR LHR REFLEX-GL3 (REAR REFLECTOR LH) X	MGRF5-51-5M0A	1		-	\$ 49.65
10	REFLECTOR RHR REFLEX-GL3/KF (REAR REFLECTOR RH) X	MGRF5-51-5L0A	1		-	\$ 49.65
11	MKD53-50-251/BRACKET, BUMPER SKYACTIV (REAR BUMPER CENTER BRACKET) <i>na</i>	MDFR5-50-251	1		-	\$ 4.64
12	REINF REAR BUMPER GJ/GL (REAR INFORCEMENT) ?	MGHK1-50-260	1		-	\$ 523.08
13	RETAINER (REAR SENSOR RETAINER INNER) X	MKD45-67-UC5A85	2		-	\$ 31.54
14	TAPE, PROTECTOR (REAR SENSOR TAPE) <i>na</i>	MBCKA-50-EM1	4		-	\$ 18.56
15	GASKET(L), RR.COMB. GL3 (REAR LAMP GASKET LH) <i>na</i>	MGRF5-51-163	1		-	\$ 52.77
16	GASKET(R), RR.COMB. GL3 (REAR LAMP GASKET RH) <i>na</i>	MGRF5-51-153	1		-	\$ 52.77
Sub-Total (Parts Price) \$						\$ 2,272.35

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE & REPLACE REAR BUMPER & REAR REINFORCEMENT. AND ALL ACCIDENT AFFECTED AREA ON REAR PORTION.	660	\$ 1,980.00
2	TO REPAIR REAR BUMPER. AND ALL ACCIDENT AFFECTED AREA ON REAR PORTION.	630	\$ 1,260.00
3	TO TRANSFER REVERSE SENSORS.	NETT	\$ 180.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	250	\$ 300.00
6	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU).	100	\$ 250.00
7	SUNDRIES.	20	\$ 50.00

Survey Date & Time:

Repair Days:

Excess:

24/05/23 @ 1130

3 days

Surveyor Remarks:

Rear - by 50010068
 Resurvey before paint

Sub-Total (Labour Price) \$

	REVISED	PRICE
Parts Price	\$ -	\$ 2,272.35
Labour Price	\$ -	\$ 4,270.00
Total (Initial Estimate)	\$ -	\$ 6,542.35
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ -	\$ 6,542.35
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ -	\$ 6,542.35
GST	8% \$	\$ 523.39

Remarks:

• This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
 • A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	601G
Vehicle No.:	SBB110G
Vehicle to be Exported:	No
Intended Deregistration Date:	29 May 2023
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 SEDAN 2.0 AT EXECUTIVE 2WD
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	PE21260466
Chassis No.:	JM6GL1072K0312838
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$23,067.00
Original Registration Date:	19 Jul 2019
First Registration Date:	19 Jul 2019
Transfer Count:	0
Actual ARF Paid:	\$24,294.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jul 2029
PARF Rebate Amount:	\$18,220.00
COE Expiry Date:	18 Jul 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$39,400.00
COE Rebate Amount:	\$22,026.00
Total Rebate Amount:	\$40,246.00

The information contained herein is correct as at 29 May 2023

OK



Mazda 6 2.0A Executive

\$101,800 Instalment \$1,153/mth

♡ Shortlist

✓ Get Warranty

📄 Loan Calculator



Overview Financial Photo Research

Depreciation	ⓘ \$14,600 / year
Reg. Date	25-Jul-2019 (6yrs 1mth 24days COE left)
Manufactured	ⓘ 2018
Mileage	74,500 km (19.4k / year)
Transmission	Auto
Engine Cap	1,998 cc
Road Tax	ⓘ \$1,210 / year
Power	121.0 kW (162 bhp) View specs of the Mazda 6 Sedan (2018)
Curb Weight	ⓘ 1,515 kg
COE	ⓘ \$36,901
OMV	ⓘ \$22,690
ARF	ⓘ \$23,766
Dereg Value	ⓘ \$38,744 as of today
No. of Owners	ⓘ 1