

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC8700A
MAKE HYUNDAI
MODEL IONIQ

DATE: 22.05.23
MVA JUMANI
DOA: 20.05.23

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$459.40
1	REAR BUMPER CENTRE MOULDING			\$451.25
1	REAR BUMPER BEAM			\$394.80
10	REAR BUMPER CLIPS			\$22.00
1	BOOTLID EMBLEM - IONIQ			\$31.30
1	BOOTLID EMBLEM - HYBRID			\$24.30
1	BOOTLID EMBLEM - H			\$28.00
1	REAR FOG ALMP			\$210.50
1	ANTENNA ASSY - SMARTK			\$40.50
1	REAR BUMPER CENTRE UNDER COVER			\$255.00
1	REAR BUMPER TOW COVER			\$98.80
1	BOOTLID COVER			\$2,549.70
1	BOOTLID GLASS LOWER MOULDING			\$145.20
	REAR WINDSCREEN GLASS - SMALL			\$584.90
1	BOOTID GLASS UPPER MOULDING			\$186.30
	SUB TOTAL		4223.45	\$5,481.95
	LESS 20%		20% 3386.76	\$1,096.39
	DISCOUNTED TOTAL			\$4,385.56
	REVERSE SENSOR			\$180.00
	REAR BOOTLID COMFORT LOGO			\$30.00
	REAR BOOTLID TEL.NOS LOGO			\$30.00
	REAR BOOTLID APPS LOGO			\$40.00
	REAR WINDSCREEN SEALANT			\$46.00
	RERA BUMPER MAT			\$50.00
	REAR NUMBER PLATE			\$55.00
	SUB TOTAL			\$431.00
	DISCOUNTED TOTAL		381	
	Labour Charge			
	PANEL BEATING			
	SPRAY PAINT			
	REMOVE / REFIX REVERSE SENSOR			
	CHECK WIRING			
	REMOVE/REFIX REAR WINDSCREEN GLASS			
	Taaphi 97495749			
	wp 22/5/23 2pm			
	1/5 Resury after repair			
	Taaphi @ Khandoca			
	03 days			
	TOTAL LABOUR		525	\$1,100.00
			500	\$600.00
			30	\$50.00
			30	\$50.00
			✓	\$120.00
			1205	
			4972.72	\$1,920.00
			48\$4000	
			3 days.	\$6,736.56