



Letter of Claims
Request of direct settlement.

We are submitting a claim on behalf of our customer Gracie Lim Ranche
NRIC 300D insured of vehicle SMT 1286 Z against
your insured vehicle number SJD 7685M (EQ)
On the accident dated on 21/5/2023 (ddmmyyyy) along
21 Sengkang West Ave.

Dated this 23 (day) of 5 (month) 20 23.

Volkswagen Group Singapore
247 Alexandra Road
Singapore 159934
DID: 63057217/63057299
HP: 93867833
shushi.tang@vw.com.sg

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



SKODA

Commercial
Vehicles

Quotation

Non binding - Preview

Page 1/2

Company
EQ INSURANCE COMPANY LIMITED
5 Maxwell Road, #17-00
Tower Block, MND Complex
Singapore 069110

Customer Details:
Ms.
GRACIE
LIM BAN CHENG
22 LORONG PUNTONG
#07-01
Singapore 576439

Document no.
Document date 23-05-2023
Customer no. 5211043754
Customer GST-ID 197800490N
Dealer 30001
Job order number 2023013723/ 1
Job order date 22-05-2023
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SMT9286Z	5T13NZC1	24-07-2020	WVGZZZ1TZKW072578	Touran Comfortline EQP 1.4 TSI 110kW DSG	34,724

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#6	280.00	302.40
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	480.00	518.40
5TA807417 GRU	Cover For Bumper Primed	1	pcs.	1,307.91	#6	1,307.91	1,412.54
5TA807568A 9B9	Spoiler Satin Black	1	pcs.	399.17	#6	399.17	431.10
WHT005263	Rivet	4	pcs.	1.32	#6	5.28	5.70
5TA807305	Bumper REINFORCEMENT	1	pcs.	766.55	#6	766.55	827.87
5TA807863	Attachment Strip	1	pcs.	80.40	#6	80.40	86.83
5TA807453	BUMPER CTR BRACKET						
	Guide Piece	1	pcs.	58.20	#6	58.20	62.86
5TA807454	LHR BUMPER BRACKET (UPPER)						
	Guide Piece	1	pcs.	58.20	#6	58.20	62.86
5TA807393	RHR BUMPER BRACKET (UPPER)						
	Guide Piece	1	pcs.	56.51	#6	56.51	61.03
5TA807394	LHR BUMPER BRACKET (SIDE)						
	Guide Piece	1	pcs.	56.51	#6	56.51	61.03
5TA945105	RHR BUMPER BRACKET (SIDE)						
	Reflector	1	pcs.	86.53	#6	86.53	93.45
	LHS REFLECTOR INNER						
	LABOUR	3	pcs.	840.00	#6	2,520.00	2,721.60
	SPRAY PAINT	3	pcs.	800.00	#6	2,400.00	2,592.00
	REVERSE SENSOR	1	pcs.	400.00	#6	400.00	432.00
	EQ DIRECT						
	DOA: 21/5/2023						
	TP VEH: SJD7685M						
	SURVEY BY:						

Quotation valid till 29-05-2023

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#6	760.00	8,195.26	8%	716.42	8,955.26	9,671.68
Total	760.00	8,195.26		716.42	8,955.26	9,671.68

Customer

Service Advisor

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



SKODA

Commercial
Vehicles

Quotation

Non binding - Preview

Page

2/2

Company
EQ INSURANCE COMPANY LIMITED
5 Maxwell Road, #17-00
Tower Block, MND Complex
Singapore 069110

Customer Details:
Ms.
GRACIE
LIM BAN CHENG
22 LORONG PUNTONG
#07-01
Singapore 576439

Document no.
Document date 23-05-2023
Customer no. 5211043754
Customer GST-ID 197800490N
Dealer 30001
Job order number 2023013723/ 1
Job order date 22-05-2023
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SMT9286Z	5T13NZC1	24-07-2020	WVGZZZ1TZKW072578	Touran Comfortline EQP 1.4 TSI 110kW DSG	34,724

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

All invoices are denominated in SGD, unless otherwise stated.