




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR23005285/Kqp3e2 Date: 05/06/2023 Code: SMR		
1. Policy Particulars :- (THIRD PARTY CLAIM)					
Insured Veh.		SHB 5553H	Veh. Inspected		SCU 685C
Policy No.			Coverage (\$)		0.00
Claim No.		TAX/05/23/2060	Excess (\$)		0.00
Assign From		HUA YEN	Assign Date		23/05/2023
2. Vehicle Particulars & Condition					
Make & Model		MAZDA 3 (A)	c.c		1496
Engine No.		HIDDEN	Year of Reg.		2021
Chassis No.		JM6BP2SAAK1103413	Colour		WHITE
Odometer		60739 KM	Steering		IN ORDER
Brakes		IN ORDER	Modification		STANDARD ALLOY RIM
General		GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/45 R18	BRIDGESTONE	6 mm	
	L/H Front Tyre	215/45 R18	BRIDGESTONE	6 mm	
	R/H Rear Tyre	215/45 R18	BRIDGESTONE	6 mm	
	L/H Rear Tyre	215/45 R18	BRIDGESTONE	6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
5. General Information					
	Accident Date	20/05/2023	Inspect Date / Time 25/05/2023 (10:02 AM)		
	Survey held at	REVOL CARZ GARAGE PTE LTD BLOCK 10, ANG MO KIO IND PARK 2A #02-18, AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		

Report Ref No. CS3/SMR23005285/Kqp3e2

Inspected By

KSC

KONG SENG CHEONG

Licensed Appraiser

KK

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.