



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23005295/Rqp3e2 Date: 12/07/2023 Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SMB 3008U	Veh. Inspected	SNH 1967X
Policy No.		Coverage (\$)	0.00
Claim No.	D23001800MFBP	Excess (\$)	0.00
Assign From	JOANNE TAN	Assign Date	23/05/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	B.M.W. X1 SDRIVE 18I LED HL XL	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	WBA32AA0805V22662	Colour	RED
Odometer	9195 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	225/50 R15	HANKOOK	6 mm
L/H Front Tyre	225/50 R15	HANKOOK	6 mm
R/H Rear Tyre	225/50 R15	HANKOOK	6 mm
L/H Rear Tyre	225/50 R15	HANKOOK	6 mm
<b>4. Description of Damages</b>			
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.		
<b>5. General Information</b>			
Accident Date	19/05/2023	Inspection Date	24/05/2023
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
<b>5a. Remarks</b>			
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
<b>5b. Estimate Days of Repair</b>			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days		