

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0501/2023/EQ
DATE : 25-May-23
WIP : 22131

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/5/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : M/S PREMIUM AUTOMOBILES PTE LTD
ADDRESS : 55 UBI ROAD 1
SINGAPORE 408699

TELEPHONE : HP +65 66900280
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : -
VEHICLE NO : **SNJ 5169 X**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 31/1/2023
ENGINE NO : DLA B79377
CHASSIS NO : WAUZZZGY1NA082008
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-May-23
PLACE OF ACCIDENT : ULU PANDAN ROAD, CLEMENTI ROAD
(OPPOSITE SUNSET WAY)

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNJ 5169 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00 ?	
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT FENDERS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00 / 1000	
4	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS AND BONNET.	\$ 3,500.00 / 1100	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: \$ 7,672.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNJ 5169 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>de</i>	1	\$	1,778.00
2	FRONT BUMPER FIXING PARTS <i>X</i>	1	\$	307.00
3	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>?</i>	2	\$	274.00
4	FRONT BUMPER GRILLE - LOWER CENTRE <i>?</i>	1	\$	458.00
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?</i>	1	\$	281.00
6	FRONT BUMPER AIR GUIDE - LH / RH <i>?</i>	2	\$	142.00
7	FRONT BUMPER SPOILER <i>?</i>	1	\$	345.00
8	FRONT BUMPER TRIM COVER - LH / RH <i>X</i>	2	\$	220.00
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>X</i>	2	\$	362.00
10	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>X</i>	2	\$	92.00
11	RADIATOR GRILLE <i>ca</i>	1	\$	1,167.00
12	RADIATOR GRILLE CLOSING ELEMENT - CENTER <i>?</i>	1	\$	223.00
13	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$	127.00
14	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$	793.00
15	FRONT BUMPER SUPPORT - LH / RH <i>?</i>	2	\$	22.00
16	FRONT BUMPER GUIDE SECTION - LH / RH <i>?</i>	2	\$	114.00
17	FRONT BUMPER SPACER PANEL COVER <i>?</i>	1	\$	94.00
18	HORN LOW TONE - LH <i>X</i>	1	\$	157.00
19	HORN HIGH TONE - RH <i>X</i>	1	\$	165.00
20	HORN BRACKET - UPPER <i>X</i>	4	\$	108.00
SUB TOTAL SPARE PARTS		:	\$	7,229.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNJ 5169 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN BRACKET - LH X	2	\$ 75.00	
22	HORN BRACKET - RH X	2	\$ 75.00	
23	RADIATOR GRILLE SENSOR - INNER ?	2	\$ 571.00	
24	FRONT AIR GUIDE GRILLE SENSOR - OUTER ?	1	\$ 286.00	
25	FRONT PARKING AID SEAL RING ✓	4	\$ 54.00	
26	BONNET 5/-	1	\$ 3,330.00	
27	BONNET IMPACT PROTECTION ✓	1	\$ 32.00	
28	BONNET STRIKER - LH / RH ?	2	\$ 260.00	
29	BONNET LOCK - LH / RH ?	2	\$ 481.00	
30	BONNET RELEASE ELEMENT ?	1	\$ 69.00	
31	BONNET BOWDEN CABLE - CENTER X	1	\$ 66.00	
32	BONNET RELEASE CABLE COVER X	1	\$ 12.00	
33	BONNET RELEASE LEVER X	1	\$ 16.00	
34	HEADLIGHT - LH / RH ?	2	\$ 8,646.00	
35	LIFT CYLINDER - LH / RH X	2	\$ 446.00	
36	LIFT CYLINDER HOSE X	1	\$ 112.00	
37	RADIATOR AIR GUIDE - UPPER ?	1	\$ 53.00	
38	RADIATOR AIR GUIDE - LH / RH UPPER ?	2	\$ 68.00	
39	RADIATOR AIR GUIDE - UPPER FRONT ?	1	\$ 34.00	
40	RADIATOR AIR GUIDE - LOWER REAR ?	1	\$ 45.00	
SUB TOTAL SPARE PARTS		:	\$ 14,731.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNJ 5169 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	RADIATOR AIR GUIDE - LH / RH LOWER ?	2	\$ 68.00	
42	RADIATOR AIR GUIDE - LOWER FRONT ?	1	\$ 28.00	
43	RADIATOR AIR GUIDE SEAL - RH ?	1	\$ 15.00	
44	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ 22.00	
45	CAUTION SIGN STICKER ?	1	\$ 17.00	
46	AIR CONDITIONER STICKER ?	1	\$ 9.00	
47	FRONT NUMBER PLATE 4 /	S/N	\$ 60.00	
48	SUNDRIES ?		\$ 600.00	
TOTAL SPARE PARTS		:	\$ 22,779.00	
TOTAL LABOUR CHARGES		:	\$ 7,672.00	
GRAND TOTAL		:	\$ 30,451.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Rasmu - 4p 90010068
: 30/05/23 A 1000
: 5 days
: EXCESS-TBA
: REPAIR / Rep 14 paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT