

Estimate

LKK AUTO CONSULTANTS PTE LTD Singapore, Singapore, Singapore, Singapore, Singapore - 575722. Contact: +65 62563561 Email: sur@lkkauto.com	Proforma Invoice No:	Date: May 25 2023
	TP Reg. No: SMM422T	Insured Reg. No: 0
	Ticket No: LKK-J000182	Accident Date: May 21 2023
Company Name: INDIA INTERNATIONAL INSURANCE Address: 64 Cecil Street,#04-02 IOB Building City: Singapore Region: Central Singapore Postal Code: 049711 Co.Reg.No: 198703792K	Policy No: D20MPC0003330	Claim No: 0
	Customer: A Aravin Kumar Vehicle: HONDA CIVIC 1.6 VTi 2019 Kilometer: 0 Color: WHITE Fuel: PETROL PH: +65 96735443 Email:	

#	Part Name	Description	Quantity	Unit Price	Payable Amount	Taxable	Parts Total
1	HEADLIGHT ASSY,R.	Part	1.00	506.92	506.92	506.92	506.92
2	FACE,FR.BUMPER	Part	1.00	434.92	434.92	434.92	434.92
3	SPACERR.FR.BUMPER SIDE	Part	1.00	7.80	7.80	7.80	7.80
4	BEAMR.FR.BUMPER UPPER	Part	1.00	23.10	23.10	23.10	23.10
5	GARNISH ASSY,R.FR.BUMPER SIDE	Part	1.00	56.92	56.92	56.92	56.92
6	SUNDRIES	Part	1.00	30.00	30.00	30.00	30.00
7	CLIP,BUMPER (17PIECES)	Part	1.00	29.32	29.32	29.32	29.32
						Taxable Value	1,088.98
						Discount Total	0.00
						Grand Total	1,088.98

#	Service	Description	Quantity	Unit Price	Payable Amount	Taxable	Labour Total
8	INSPECT FR LIGHTING MECHANISMS & FOCUS	Labour	-	225.00	225.00	225.00	225.00
9	REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON	Labour	-	585.00	585.00	585.00	585.00
10	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	Labour	-	468.00	468.00	468.00	468.00
						Taxable Value	1,278.00
						Discount Total	0.00
						Grand Total	1,278.00

	Parts Total	1,088.98
	Labour Total	1,278.00
	GST Total	0.00
	Grand Total	2,366.98
	Balance	2,366.98

I certify that the work has been done to my satisfaction and that I have taken delivery of the vehicle in good condition, with all items / valuables and parts intact.

Customer / Authorized Signatory

Service Advisor Signature

Cashier / Authorized Signature