

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No.	: SQT23001576	Page	1
Registration No	: SMM422T	Date	: 23. May 2023		
Chassis No	: MRHFC5650KT000245	Customer No.	: WI007		
Model	: CIVIC 1.6 VTI YM2019	Svc Advisor	: LEE CHEN SIN		
Owner's Name	: A ARAVIN KUMAR	Engine No	: R16B25510250		
Ins Policy No.	:	Date Time	: 23. May 2023 2:03:23 PM		
Date of Accident	: 21/5/2023	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO:15440 POLICY/CLAIMS NO:D20MPC0003330 OWNER:A ARAVIN KUMAR ACC DATE:21/05/2023 SURVEYED BY: DATE: AUTHORIZED ON : REF NO :						
33100-TEC-Q01	HEADLIGHT ASSY,R.	1	675.90	25	506.92	40.55	547.47
71124-TEA-T01	EXTENSION ASSYR.FR.GRILLE	1	98.80	25	74.10	5.93	80.03
71121-TEA-T51	BASE,FR.GRILLE	1	167.00	25	125.25	10.02	135.27
71125-TEA-T01	MOLDINGFR.GRILLE	1	115.80	25	86.85	6.95	93.80
75700-TBA-A00	EMBLEM	1	17.40	25	13.05	1.04	14.09
90301-ST0-003	NUT,PUSH 3MM	2	2.10	25	3.15	0.25	3.40
71101-TEA-T50ZA	FACE,FR.BUMPER	1	579.90	25	434.92	34.79	469.71
91505-TM8-003	CLIP,BUMPER	17	2.30	25	29.32	2.35	31.67
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.62	8.42
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.62	8.42
71140-TEA-T00	BEAMR.FR.BUMPER UPPER	1	30.80	25	23.10	1.85	24.95
71180-TBA-K50	GARNISH ASSY,R.FR.BUMPER SIDE	1	75.90	25	56.92	4.55	61.47
33900-TEY-Y01	LIGHT ASSY R FR F	1	288.90	25	216.67	17.33	234.00
71130-TEA-T00	BEAM COMPFR.BUMPER	1	399.20	25	299.40	23.95	323.35
71150-TEA-T00	BEAM COMPFR.BUMPER CENTER UPP	1	248.00	25	186.00	14.88	200.88
				Sum Item	2071.25	165.68	2,236.93
BOSUN	SUNDRIES	1	100.00		100.00	8.00	108.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	280.00		280.00	22.40	302.40

Printed on 23/5/2023 2:12:10 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No.	: SQT23001576	Page	2
Registration No	: SMM422T	Date	: 23. May 2023		
Chassis No	: MRHFC5650KT000245	Customer No.	: WI007		
Model	: CIVIC 1.6 VTI YM2019	Svc Advisor	: LEE CHEN SIN		
Owner's Name	: A ARAVIN KUMAR	Engine No	: R16B25510250		
Ins Policy No.	:	Date Time	: 23. May 2023 2:03:23 PM		
Date of Accident	: 21/5/2023	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
BKBU01R	REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON	1	1500.00		1500.00	120.00	1620.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(2P)	1	1300.00		1300.00	104.00	1404.00
Sum Labor					3180.00	254.40	3,434.40

Survey By	_____						
Date & Time	_____						
Excess	_____						
Status	_____						
Signature	_____						
					Total Amount	5,251.25	420.08
					Total (Inclusive of GST)		5,671.33

Printed on 23/5/2023 2:12:10 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.