



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/AIG23003203/Wvp3-1

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #09-16
AIG BUILDING
SINGAPORE 079120

Ref: ~~CS3/AIG23003203/Wvp3-1~~
Date: ~~20/03/2020~~ 24/05/2023

Code: AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SNH 238Z	Veh. Inspected	GBL 7620C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	VILASINI PERUMAL BERNARD LER	Assign Date	20/03/2020 24/05/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/03/2023	Inspection Date	29/03/2023
Survey held at	POLYMATH GARAGE PTE LTD 10 KAKI BUKIT ROAD 2 #03-01 FIRST EAST CENTRE S(417868)		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--