

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

28/12/2022

CHINA TAIPING INSURANCE SINGAPORE PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Page: 1
Vehicle No: SKZ5488B
Vehicle Model: MAZDA 5
Est No: CD3365
Claims ref:
Accident Date: 20/05/23
In Charge: BILLY
Remarks:

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	HEADLAMP ASSY RH	1 PC	\$ 1,482.00	\$ ✓ 1,482.00 <i>ann</i>
2	FRONT BUMPER	1 PC	\$ 1,108.00	\$ ✓ 1,108.00 <i>ty</i>
3	FRONT BUMPER RETAINER RH	1 PC	\$ 39.00	\$ ✓ 39.00 <i>da</i>
4	FRONT BUMPER CLIPS	10 PC	\$ 5.90	\$ ✓ 3059.00 <i>ne, 30</i>
5	FOG LAMP GARNISH RH	1 PC	\$ 56.00	\$ 56.00 <i>nn</i>
6	WASHER TANK	1 PC	\$ 125.00	\$ ✓ 125.00 <i>de</i>
7	FRONT FENDER RH	1 PC	\$ 322.00	\$ ✓ 322.00 <i>de</i>
8	FRONT FENDER COWLING RH	1 PC	\$ 210.00	\$ ✓ 210.00 <i>de</i>
9	FRONT FENDER COWLING CLIPS	10 PC	\$ 5.60	\$ 20 56.00 <i>ne, 20</i>
10	FRONT FENDER CORNER GARNISH RH	1 PC	\$ 48.10	\$ 48.10 <i>xnn</i>
11	FRONT KNUCKLE HUB RH	1 PC	\$ 150.00	\$ 150.00 <i>xnn</i>
12	FRONT KNUCKLE BEARING RH	1 PC	\$ 159.00	\$ 159.00 <i>xnn</i>
13	FRONT KNUCKLE ARM RH	1 PC	\$ 386.00	\$ 386.00 <i>xnn</i>
14	FRONT LOWER ARM RH	1 PC	\$ 410.00	\$ 410.00 <i>xnn</i>
15	FRONT SHOCK ABSORBER RH	1 PC	\$ 265.00	\$ 265.00 <i>xnn</i>
16	FRT FENDER INNER PANEL RH (REPAIR)	1 PC		
LIST TOTAL S\$			3286	\$ 4,875.10 <i>3286.00</i>
20% DISCOUNT S\$			2628.80	\$ (975.02) <i>657.20</i>
			sn 50	\$ 3,900.08 <i>112628.80</i>
SPECIAL NET ITEMS:				<i>50.00</i>
1	FRONT SPORT RIM RH	1 PC	480.00	\$ 480.00
SPECIAL NET TOTAL S\$			480	\$ 480.00 <i>530.00</i>

LABOUR CHARGE:

- 1 TO KNOCK & STRAIGHTEN FRONT FENDER INNER PANEL RH,
REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722
 Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

ESTIMATE

28/12/2022

CHINA TAIPING INSURANCE SINGAPORE PTE LTD
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

Page: 1
 Vehicle No: SKZ5488B
 Vehicle Model: MAZDA 5
 Est No: CD3365
 Claims ref:
 Accident Date: 20/05/23
 In Charge: BILLY
 Remarks:

No	Description	Qty	U. Price	Amounts S\$
	ALL CONNECTION			\$ 600.00 400
2	SPRAY PAINT FRONT BUMPER, FRONT FENDER INNER PANEL RH FRONT FENDER RH, FRONT DOOR RH			\$ 800.00 ⁶⁰⁰
3	REMOVE & REPLACE FRONT UNDER CARRIAGE SUSPENSION RH			\$ 150.00 ^{photo} xnn
4	COMPUTER WHEEL ALIGNMENT			\$ 60.00 ✓
5	RUST PROOF AFFECTED AREAS			\$ 30.00 ✓
	TOTAL LABOUR COST S\$		1090	\$ 1,640.00 ^{21090.00}

AMOUNT S\$ \$ 6,020.08
 GST @ 8% \$ 481.61
 AMOUNT DUE S\$ \$ 6,501.69

Customer's Signature

MOVA AUTOMOTIVE PTE LTD

Tanpikun 92495749 / 62563561
inf 17/7/23 @ 430pm
1/3 Body after repair
Tanpikun e (handwritten)
6 delays

2628.80
 50
 480
 1090
 4248.80
 1/s\$3400
 4 days #

1) PAINT 2628.80
 2) GUST 520.00
 3) LABOUR 1090.00
 4248.80
 - 849.76 less 20%
 3399.04

LEAVE SUM \$ 3400.00

PLEASE ADVISE.
 THANK YOU
 BILLY LAM