




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: KITTY TEO			Ref: CS3/HSB23005334/Uvp3e2 Date: 09/06/2023 Code: HSB	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 638K	Veh. Inspected	SNC 2804C
	Policy No.		Coverage (\$)	0.00
	Claim No.	S3M04MTZ	Excess (\$)	0.00
	Assign From	KITTY TEO	Assign Date	25/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	GK82201655	Colour	WHITE
	Odometer	35559 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm
	L/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.			
5. General Information				
	Accident Date	21/05/2023	Inspect Date / Time	29/05/2023 (10:00 AM)
	Survey held at	2ND AUTO PTE LTD 15 KAKI BUKIT ROAD 4, #01-53, BARTLEY BIZ CENTRE, SINGAPORE 417808		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	

Report Ref No. CS3/HSB23005334/Uvp3e2

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.