



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

HL ASSURANCE PTE LTD  
11 KEPPEL ROAD  
#11-01 ABI PLAZASINGAPORE 089057

Ref: CS/HLA23005335/p3

Date: 25/05/2023

Code: HLA

#### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLU 7035B	<b>Veh. Inspected</b>	GBC 9640D
<b>Policy No.</b>	MP308804	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MPC04277	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ROMEO JONNALYN	<b>Assign Date</b>	25/05/2023

#### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>		<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>		<b>Colour</b>	
<b>Odometer</b>	-	<b>Steering</b>	
<b>Brakes</b>		<b>Modification</b>	
<b>General</b>			

#### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>			mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>			mm
<b>L/H Rear Tyre</b>			mm

#### 4. Description of Damages

--

#### 5. General Information

<b>Accident Date</b>	21/05/2023	<b>Inspection Date</b>	
<b>Survey held at</b>	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--