



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL

INV No. AC2303573

50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWER
SINGAPORE 048623

INV Date 07/06/2023
Reference CS3/SMO23005344/Knp3m
Code SMO

PROFESSIONAL SERVICE FEE

Vehicle No. SFM 1881C
Insured Veh. SMM 4343L
Claim No. CMTD2302101/RUC
Policy No. D22MTPV01010519
Accident Date 22/05/2023
Inspection Date 25/05/2023

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 29.05.2023)	10.00
Subtotal	110.00
GST (8%)	8.80
Grand Total	118.80

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

SML