



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23005372/Uvp3e2 Date: 01/06/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 900Y	Veh. Inspected	SMY 3180H	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/05/23/2073	Excess (\$)	0.00	
Assign From	ASHLENE LEE	Assign Date	25/05/2023	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI OUTLANDER (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	GF7W0701062	Colour	BLUE	
Odometer	36115 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/05/2023	Inspection Date	26/05/2023	
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	