

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : **Allianz Insurance Singapore Pte Ltd**
79 Robinson Road
#09-01
Singapore 068897

Claim Details
Case Ref. No. : TP/052023/6254
Date : 24-05-2023
Accident Date : 23-05-2023

Vehicle Details

Make & Model : Toyota C-HR HYBRID 1.8G CVT
Chassis No : ZYX102024806
Registration No : SJK2338L

Third Party Vehicle Details

Registration No : GBE663L

S/N	Description	Qty	Amount (S\$)
1	REAR BUMPER	1.00	820 7 \$220.00
2	REAR BUMPER LOWER PAD	1.00	de \$220.00
3	REAR BUMPER TOWING COVER	1.00	cut \$20.00
4	REAR BUMPER CLIPS	10.00	net \$20.00
5	REAR BUMPER REINFORCEMENT	1.00	8 \$210.00
			\$690.00
Margin: 10%			\$69.00
			\$759.00
6	REAR BUMPER SENSOR	1.00	7 \$280.00
7	TO REPAIR DAMAGES	1.00	200 \$480.00
8	TO SPRAY PAINTING	1.00	400 \$480.00
Subtotal w/o GST:			\$1,999.00

Tan LK 97495749
WP' 26/5/23 5pm
P/P Resurvey new parts
2 days
Tan LK 97495749

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Tan Leng Leng

This is a computer-generated document. No signature is required.