



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23005391/Anp3m4 Date: 10/07/2023 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 6111H	Veh. Inspected	SKB 4321G	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/05/23/2077	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	26/05/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	KIA CERATO FORTE	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	KNAFU411MB5376037	Colour	BLUE	
Odometer	186371 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	CONTINENTAL	6 mm	
L/H Front Tyre	185/65 R15	CONTINENTAL	6 mm	
R/H Rear Tyre	185/65 R15	CONTINENTAL	6 mm	
L/H Rear Tyre	185/65 R15	CONTINENTAL	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	24/05/2023	Inspection Date	26/05/2023	
Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	