



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS3/LPC23001242/Rvy3-1

LONPAC INSURANCE BHD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: ~~CS3/LPC23001242/Rvy3~~  
Date: ~~06/02/2023~~ 29/05/2023  
Code: LPC2

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

<b>Insured Veh.</b>	YN 5241T	<b>Veh. Inspected</b>	SNG 1169M
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	22/23/23/VC05/026926	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GERALD POH	<b>Assign Date</b>	<del>06/02/2023</del> 29/05/2023

## 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>		<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>		<b>Colour</b>	
<b>Odometer</b>	-	<b>Steering</b>	
<b>Brakes</b>		<b>Modification</b>	
<b>General</b>			

## 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>			mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>			mm
<b>L/H Rear Tyre</b>			mm

## 4. Description of Damages

--	--

## 5. General Information

<b>Accident Date</b>	01/02/2023	<b>Inspection Date</b>	07/02/2023
<b>Survey held at</b>	SK GARAGE NO. 5 SOON LEE STREET #01-34 SINGAPORE 627607		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.