

A-PAC Adjusters & Surveyors Pte Ltd

Company Registration No. : 201705143H
28 Sin Ming Lane #06 - 141, Midview City, Singapore 573972
Tel : +65 6904 4922 Fax : +65 6904 4922

A-PAC

ADJUSTER REPORT

Mr Raj.

Primero Racing

No. 20 Bukit Batok Crescent Enterprise Centre
#01-19
Singapore 658080

Our Ref : APAC/IND/21-09001

Date : 11/12/2021

DESCRIPTION & IDENTIFICATION OF SURVEYED VEHICLE

Name of Third Party	: Mohammad Illyas B Mohammad Jais	Third Party Vehicle	: FBM 7681 X
Name of Insurer	: NTUC Income Insurance	Policy No	: 5121157609
Make & Model	: BMW S1000XR	Engine No	: 104EC23159835
Registration Date	: 4/3/2016	Chassis No	: WB10D0304GZ444579
Engine Capacity	: 999 cc	Colour	: Red
Odometer	: -	Market Value (S\$)	: 30,000.00
Sum Insured (S\$)	: Market Value/New Car Price	COE/PARF Rebate (S\$)	: 1,880.00

CONDITION OF VEHICLE

General Condition	: Good	Modification	: No
Steering	: Serviceable	Air-Conditioner	: Yes
Audio Player	: Yes	Seat Belts	: Yes
Handbrake	: Serviceable	Footbrake	: Serviceable
Wing Mirror	: Yes	Paint Work	: Good

CONDITION OF TYRES (The below values represent the remaining tyre treads depth)

Front Tyre Size	: 120/70ZR17	Rear Tyre Size	: 120/80ZR17
Front Left Side	: Battlax 8mm	Rear Left Side	: Battlax 8mm
Front Right Side	: Battlax 8mm	Rear Right Side	: Battlax 8mm

GENERAL DESCRIPTION OF DAMAGE

The inspected vehicle sustained damage at the **RIGHT** portion.

Visual inspection noted that the handle, front right lower farring, glider, front pedal assembly, rear tail fender and among other parts were affected.

All stated damage is subject to consistency of the accident reports.



RECOMMENDED PARTS

No.	Qty	Part No.	Descriptions	Condition	Repairer	Adjusted	
1	1	-	HANDLE	Bent	435.50	435.50	✓
2	1 SET	-	HANDLE GUARD	Grazed	235.50	235.50	✓
3	1	-	HANDLE BALANCER	Grazed	85.90	85.90	✓
4	1 SET	-	MIRROR	Grazed	275.90	275.90	✗ nn
5	1	-	FRONT RIGHT LOWER FARRING	Grazed	535.90	535.90	✓
6	1	-	FRONT RIGHT LOWER INNER FARRING	Grazed	475.50	475.50	✓
7	2 SETS 1	-	GLIDER frame slider RH	Grazed	350.00	350.00	170 ✓
8	1	-	FRONT LOWER COVER	Cut	425.00	425.00	✗ nn
9	1	-	FRONT PEDAL ASSEMBLY WITH BRACKET	Bent	625.00	625.00	✗ nn
10	1	-	EXHAUST SIDE COVER PROTECTOR	Grazed	275.10	275.10	✗ nn
11	1	-	REAR RIGHT SIGNAL	Cut	170.00	170.00	✓
12	1	-	REAR NUMBER PLATE	Bent	40.00	40.00	✓
13	1	-	REAR TAIL FENDER	Bent	335.00	335.00	✗ nn

2148.30
-10%
1933.47

Sub Total (\$\$) :	4,264.30	4,264.30	
Discount (10%) :	426.43	426.43	
Total Parts (\$\$) :	3,837.87	3,837.87	

RECOMMENDED SPECIAL NETT ITEMS

No.	Qty	Part No.	Descriptions	Condition	Repairer	Adjusted	
1	1	-	RIGHT CARRIER BOX (RED)	Grazed	1,335.00	1,335.00	500 ✓
2	1	-	RIGHT CARRIER BRACKET	Bent	375.00	375.00	220 ✓

720

Sub Total (\$\$) :	1,710.00	1,710.00	
--------------------	----------	----------	--

RECOMMENDED LABOUR

No.	Descriptions	Repairer	Adjusted	
<u>LABOUR ITEMS</u>				
1	REFIX, REMOVE, REPLACE OF AFFECTED PARTS.	900.00	700.00	300
<u>PAINTWORK LABOUR</u>				
1	SPRAY PAINT AT AFFECTED PORTION.	700.00	500.00	400

700

Total Labour (\$\$) :	1,600.00	1,200.00	
-----------------------	----------	----------	--

COST OF CLAIMS

	Repairer	Adjusted
1 PARTS	3,837.87	3,837.87
2 SPECIAL NETT ITEMS	1,710.00	1,710.00
3 LABOUR	900.00	700.00
4 PAINTWORK LABOUR	700.00	500.00

3353.47

Gross Total (\$\$) :	7,147.87	6,747.87	
GST 7.00% (\$\$) :	-	-	
Total Amount (\$\$) :	7,147.87	6,747.87	

3 days

L/S - 2682.77
= 2700