$51\,UBI\,AVE\,1, \#01-25\,PAYA\,UBI\,INDUSTRIAL\,PARK, SINGAPORE\,408933\,\,TEL:\\ (065)\,62563561\,\,FAX:\\ (065)\,62564315$

Immediate Advice

To: HSBC LIFE (SINGAPORE) PTE LTD DATE: 5/6/2023

Survey details

Date of loss	20/5/2023
Date of appointment	29/5/2023
Date of survey	30/5/2023
Location of survey	DYNASTY MOTOR PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle number	FBU 5198X
Make and Model	HONDA ADV 160
Date of registration	20/12/2022
Excess	
Market Value	\$19,000.00
Parf Rebate	\$12,010.00
Nett Loss	\$6,990.00

Repair details

Proposed/Revised repair cost:

Parts	
"Check items (Estimated)	
Labour	
Total	
Lump Sum (Estimated)	

Number of days of repair 3 days (est)

Remarks:

Damages Consistent

The estimated repair cost of the damaged vehicle is in the region of \$2,000.00-\$3,000.00