



1

of 2 ?

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref: CS/CTI23005459/Uvp3

3 ANSON ROAD #16-00

Date: 30/05/2023

SPRINGLEAF TOWERSINGAPORE 079909

Code: CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SME 8480P	Veh. Inspected	FBP 6668B
Policy No.	DMPCSNW00210792201	Coverage (\$)	0.00
Claim No.	SNM23D203395/C02	Excess (\$)	0.00
Assign From	CECILIA LEE	Assign Date	30/05/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	10/05/2023	Inspection Date	30/05/2023
Survey held at	SANFU MOTOR PL 1 KAKI BUKIT AVENUE 6 #02-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	--