

Estimate

DING AUTO PTE LTD 176 , Sin Ming Dr, #04-06 Sin Ming AutoCare, Singapore, Singapore, Singapore - 575721. Contact: +65 9231 3123 Email: desmond@insurlogic.co	Proforma Invoice No:	Date: May 29 2023
	Ticket No: DAP-J000010	Vehicle No: SLT8052A
	Engine No: 2ZR8078645	
	Vehicle: TOYOTA PRIUS 1.8 E 2017 Kilometer: 166931 Color: BLACK Fuel: PETROL PH: +65 97849075 Email: randy.lhts@gmail.com	
Customer Name: General Piping Services And Supplies Pte Ltd Mobile No: +65 97849075		

#	Part Name	Description	Quantity	Unit Price	Taxable	Parts Total
1	FRONT BUMPER	Part	1.00	220.00	CM 220.00	✓ 220.00
2	BONNET	Part	1.00	374.00	B 374.00	✓ 374.00
3	BONNET LOCK	Part	1.00	88.00	B 88.00	✓ 88.00
4	RADIATOR ASSY	Part	1.00	715.00	715.00	✓ 715.00
5	FAN MOTOR	Part	1.00	313.50	1.31 313.50	✓ 313.50
6	A/C SUCTION PIPE	Part	1.00	247.50	1.24 247.50	✓ 247.50
7	FRONT BUMPER REINFORCEMENT	Part	1.00	302.50	1.30 302.50	✓ 302.50
8	FRONT FENDER LH	Part	1.00	324.50	B 324.50	✓ 324.50
9	HEADLAMP ASSY RH	Part	1.00	1,155.00	1.15 1,155.00	✓ 1,155.00
10	HEADLAMP ASSY LH	Part	1.00	1,155.00	1.15 1,155.00	✓ 1,155.00
11	CONDENSOR ASSY	Part	1.00	770.00	1.77 770.00	✓ 770.00
12	FAN BLADE	Part	1.00	115.50	1.11 115.50	✓ 115.50
13	A/C DISCHARGE PIPE	Part	1.00	181.50	1.18 181.50	✓ 181.50
14	BATTERY TRAY	Part	1.00	66.00	CM 66.00	✓ 66.00
15	FRONT BUMPER RETAINER RH	Part	1.00	44.00	0.44 44.00	✓ 44.00
16	FRONT BUMPER RETAINER LH	Part	1.00	44.00	CM 44.00	✓ 44.00
17	FRONT BUMPER FOAM	Part	1.00	66.00	CM 66.00	✓ 66.00
18	BONNET HINGE RH	Part	1.00	44.00	0.44 44.00	✓ 44.00
19	BONNET HINGE LH	Part	1.00	44.00	B 44.00	✓ 44.00
20	BONNET INSULATOR	Part	1.00	209.00	CM 209.00	✓ 209.00
21	BONNET STAND	Part	1.00	33.00	1.33 33.00	✓ 33.00
22	FRONT GRILLE	Part	1.00	198.00	CM 198.00	✓ 198.00
23	FRONT LOWER GRILLE	Part	1.00	99.00	1.09 99.00	✓ 99.00
24	WIPER PANEL	Part	1.00	308.00	1.30 308.00	✓ 308.00
25	FAN SHROUD ASSY	Part	1.00	159.50	1.15 159.50	✓ 159.50
26	WASHER TANK	Part	1.00	88.00	1.88 88.00	✓ 88.00
27	EXPANSION TANK	Part	1.00	99.00	1.09 99.00	✓ 99.00
28	AIR DUCT	Part	1.00	71.50	1.71 71.50	✓ 71.50
29	AIR HOSE	Part	1.00	55.00	1.55 55.00	✓ 55.00
30	ENGINE LOWER COVER	Part	1.00	132.00	1.13 132.00	✓ 132.00
31	FRONT BUMPER BADGE	Part	1.00	55.00	1.55 55.00	✓ 55.00
32	FRONT BUMPER SIDE COVER RH	Part	1.00	60.50	1.60 60.50	✓ 60.50
33	FRONT BUMPER SIDE COVER LH	Part	1.00	60.50	1.60 60.50	✓ 60.50
34	FRONT BUMPER TOW CAP RH	Part	1.00	27.50	1.27 27.50	✓ 27.50
35	FRONT BUMPER TOW CAP LH	Part	1.00	27.50	1.27 27.50	✓ 27.50
36	FRONT BUMPER UPPER SEAL	Part	1.00	38.50	1.38 38.50	✓ 38.50
37	BONNET FRONT SEAL	Part	1.00	55.00	1.55 55.00	✓ 55.00

Part Name	Description	Quantity	Unit Price	Taxable	Parts Total
38 FRONT GRILLE CTR BRACKET	Part	1.00	55.00	55.00	55.00
39 FRONT SUPPORT UPPER PANEL	Part	1.00	77.00	77.00	77.00
40 FRONT SUPPORT CTR PANEL	Part	1.00	165.00	165.00	165.00
41 FRONT SUPPORT LOWER PANEL	Part	1.00	214.50	214.50	214.50
42 FRONT UPPER GARNISH	Part	1.00	143.00	143.00	143.00
43 FRONT FENDER BRACKET LH	Part	1.00	55.00	55.00	55.00
44 FRONT FENDER INNER SHIELD LH	Part	1.00	148.50	148.50	148.50
45 WIPER PANEL END COVER RH	Part	1.00	27.50	27.50	27.50
46 WIPER PANEL END COVER LH	Part	1.00	27.50	27.50	27.50
47 HEADLAMP BALLAST LH	Part	1.00	418.00	418.00	418.00
48 RADIATOR AIR GUIDE RH	Part	1.00	71.50	71.50	71.50
49 RADIATOR AIR GUIDE LH	Part	1.00	71.50	71.50	71.50
50 FAN BLADE - RADIATOR	Part	1.00	137.50	137.50	137.50
51 FAN MOTOR - RADIATOR	Part	1.00	313.50	313.50	313.50
52 INVERTER COOLER TANK	Part	1.00	137.50	137.50	137.50
53 AIR CLEANER HOUSING ASSY	Part	1.00	418.00	418.00	418.00
54 AIR INTAKE LOWER RESONATOR	Part	1.00	93.50	93.50	93.50
55 HORN - HIGH PITCH	Part	1.00	77.00	77.00	77.00
56 ENGINE LOWER SIDE COVER LH	Part	1.00	77.00	77.00	77.00
57 FRONT WINDSCREEN SIDE MOULDING LH	Part	1.00	165.00	165.00	165.00
58 LABOUR - BODY REPAIR, PANEL BEAT & STRAIGHTEN/ALIGN - ACCIDENT AREA	Part	1.00	1,400.00	1,400.00	1,400.00
59 LABOUR - SPRAY PAINT - FRONT BUMPER, BONNET, FRT FENDER X2, FRT DOOR LH & SUPPORT PANEL	Part	1.00	1,400.00	1,400.00	1,400.00
60 REFILL - RADIATOR COOLANT	Part	1.00	80.00	80.00	80.00
61 REFILL - AIR COND GAS	Part	1.00	80.00	80.00	80.00
62 FRONT NUMBER PLATE & FRAME	Part	1.00	35.00	35.00	35.00
63 FRT BUMPER, GRILLE, INNER SHIELD, PANEL & GARNISH - CLIPS	Part	1.00	150.00	150.00	150.00
64 HEADLAMP ECU - DIAGNOSIS & RE-SETTING	Part	1.00	350.00	350.00	350.00

NOT AUTHORIZED
 U/Rup @ 8950/-
 Return After Paint

Taxable Value
 14,434.50
 Discount Total 0.00
 Grand Total
 14,434.50

7 days	Parts Total	14,434.50
	Labour Total	0.00
	GST Total	0.00
	Grand Total	14,434.50
	Balance	14,434.50

I certify that the work has been done to my satisfaction and that I have taken delivery of the vehicle in good condition, with all items / valuables and parts intact.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: