

ASS. REC. BY:

REF:

HSB / 23005468 / Kqp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Vsh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / 8/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / ESI not ready

2.16 11.30h @ 3150h Cohn (Red @ 1724.37, 35%)

Date/Time, File Pass to?

1) 23/6 11.30h

Date/Time, File Return to?

2)

: Prel. Report

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS - SI

Fees

Others

TOTAL

Add Fee:

: Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format:

Smart Claims - TP

Lump Sum / I.B.L. (\$)

350

Not Notified
11 Pm 83150p
Preserving After Paint
6 days

EK 6006 C

Date : 31.05.2023

Quantity	Description/Particular	Unit Price	Amount	
1 PC	REAR BOOLTID		Rs 584	28
1 PC	REAR BOOTLID EMBLEM(ALTIS)		Rs 45	80
1 PC	REAR BOOTLID EMBLEM(VVTI)		Rs 36	40
1 PC	REAR BOOTLID LOCK		Rs 45	00
1 PC	REAR BUMPER		Rs 389	99
2 PCS	REAR BUMPER BRACKET@21		Rs 42	00
2 PCS	REAR BUMPER SIDE RETAINER@22		Rs 44	00
2 PCS	REAR BOOTLID HINGE@58		Rs 116	00
1 PC	REAR PANEL		Rs 388	70
2 PCS	REAR PANEL GANISH		Rs 156	00
2 PCS	REAR LAMP@280		Rs 560	00
2 PCS	REAR BOOLTID REFLECTOR@90		Rs 180	00
2 PCS	REAR PANEL LOWER PANEL@80		Rs 160	00
12 PCS	LOWER PANEL RIVET@2.0		Rs 24	00
1 PC	REAR SPARE TYRE BOARD		Rs 64	00
1 PC	REAR SPARE TYRE PANEL		Rs 437	00
1 PC	REAR BOOTLID RUBBER		Rs 59	00
1 PC	ANTENNA BOX		Rs 189	00
1 PC	REAR BOOLTID EMBLEM(TOYOTA LOGO)		Rs 58	00
	TOTAL LESS 25		2684	37

Received the above goods in good order and condition

Received by

E.&O.E.

LKK Auto Consultants hereby notify RC AUTO

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be **Authorised S**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date:

Authorised Signature

ESTIMATE RC AUTO

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722

Tel : 97619383 Email: rcauto5555@gmail.com

Reg. No. 53199168K

EK 6006 C

Date : 31.05.2023

Quantity	Description/Particular	Unit Price	Amount	
	TO RESPRAY JOB		800	00
	TO RENEW ABOVE PARTS		1000	00
	ANTI RUST		80	00
	TO CHECK WIRING		30	00
1 SET	REVERSE SENSORS		<i>Net</i> 280	00
			4874	37

Received the above goods in good order and condition

for RC AUTO

Received by

E.&O.E.

Authorised Signature