



Sin Ming Autocare BFG Pte Ltd
 176 Sin Ming Drive
 #02-05 Sin Ming Autocare
 Singapore 575721
 Tel : 6455 0600 | Fax : 6455 6192
 Website: www.autocare.com.sg
 GST Reg. No: 20-0210033-N

Allianz Insurance Singapore Pte Ltd
 79 Robinson Road
 #09-10
 Singapore 068897
 Attn: Motor Claim Dept

Not Withain
1/1/2023
Penney After Pain
4 days

ESTIMATE
 VEHICLE NO: SLF4564P
 MAKE/MODEL: TOYOTA
 HARRIER
 DATE: 26.05.2023

CHASSIS : ZSU600081025

No.	Descriptions	Qty	Unit Price	Amount S\$
LIST ITEM:				
1	TAIL GATE	1	2,126.40	2,126.40 ✓
2	TAIL GATE WEATHERSTRIP	1	446.90	446.90 X
3	TAIL GATE LOCK	1	320.15	320.15 X
4	TAIL GATE EMBLEM LOGO	1	85.60	85.60 ✓
5	TAIL GATE EMBLEM HARRIER	1	123.15	123.15 ✓
6	TAIL GATE GARNISH OUTER	1	1,055.20	1,055.20 X
7	REAR BODY PANEL	1	1,006.40	1,006.40 ?
8	REAR BODY PANEL TOP GARNISH	1	438.30	438.30 X
9	REAR BUMPER	1	1,744.70	1,744.70 ✓
10	REAR BUMPER SIDE RETAINER LH	1	85.60	85.60 X
11	REAR BUMPER LOWER COVER CLIPS	8	5.50	44.00 ✓
12	REAR BUMPER REFLECTOR LH	1	96.80	96.80 X
13	REAR WINDSCREEN MOULDING LOWER	1	101.50	101.50 ✓
14	REAR WINDSCREEN MOULDING RH	1	60.50	60.50 ✓
15	REAR WINDSCREEN MOULDING LH	1	60.50	60.50 ✓
16	REAR BEZA SENSOR	1	285.15	285.15 X
17	REAR BUMPER LOWER GARNISH	1	566.00	566.66 X
18	REAR TAIL GATE REFLECTOR LH	1	608.60	608.60 ?
Sub Total (S\$) :				9,256.11
Discount (25%) :				2,314.03
Total Parts (S\$) :				6,942.08

SPECIAL NETT ITEMS

1	REAR BUMPER REVERSE SENSOR COVER LH CENTRE	1	44.50	44.50 X
2	REAR GLASS SEALANT	1	50.00	50.00 ✓
3	REAR REVERSE SENSOR SIDE LH	1	280.00	280.00 ?
Sub Total (S\$) :				374.50

LABOUR:

1	TO DISMANTLE & REPLACE DAMAGE PARTS,PANEL BEAT WHERE NECESSARY	1,200.00	4001
2	TO PUTTY,APPLY PRIMER & SPRAY PAINT ON AFFECTED PORTION	1,000.00	4401
3	TO APPLY RUST PROOFING ON REPAIR	80.00	301
4	TO REMOVE/REFIT REAR GLASS TO FACILITATE REPAIRS	150.00	1201
5	TO REMOVE/TRANSFER REAR TAILGATE MECHANISMS	120.00	601
6	TO CHECK WIRING FUNCTIONS	60.00	201

Total Labour (S\$) :

2,610.00

Total Amount (S\$) :

9,552.08

for Sin Ming Autocare BFG Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: