

Taught

CS/CT123005530/TVP3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop. m/s

of

Insured: SDL 10K

Policy No. DMPCSNW00172502202

Claims No. SNM23D201193/C02/TOHHS

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	

Bal. or Market Value:

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Item	Unit	3 Val.: Yes or No
Lum Sum	%	2/6

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Person Contacted:

Date / Time

Action / Instruction

29/7/23	Lump Sum \$4700 confirmed by email (Red 25,186.50, 84%)
---------	---

Date/Time, File Pass 10?

ix

Date/Time, File Return to?

2) 2/8/23-typist

Flowchart Format : Merimen

Lamp Size / LEH / 4700

Days Of Repair: 7

Resurvey No. of Trip:

Add Fee: | : Site Insp (\$

☐: Interview (\$

□: Tech. Invs (\$)

☐ Weekend (S)

Survey Fee:

Transportation:

1) $S + RS \rightarrow SI$

Photos

Others

TOTAL

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT
#01-49 SINGAPORE 415875
Tel: +65 64524457
Fax: +65 64524584

Chassis number: FEB21EA21601

	\$	2,174.00
Parts less 25%	\$	543.50
Total:	\$	1,630.50

No.	Special Nett Items	Qty	Amount S\$
1	Wooden tailgate	1	\$ 24 2,200.00
2	Wooden tailgate frame	1	\$ 65 1,850.00
2	Wooden tailgate lower member	1	\$ Cur 1,600.00
2	Wooden tailgate lower member fasteners	1set	\$ 150 150.00
3	Wooden tailgate "60km/h" sticker	1	\$ 28 28.00
4	Wooden tailgate "23pax" sticker	1	\$ 28 28.00
5	Wooden tailgate RH side hinge	1	\$ 340 340.00
6	Wooden tailgate RH centre hinge	1	\$ x 340.00
7	Wooden tailgate LH centre hinge	1	\$ x 340.00
8	Wooden tailgate LH side hinge	1	\$ x 340.00
9	Rear number plate	1	\$ x 340.00
10	Wooden step	1	\$ x 50.00
11	Rear RH chassis wooden member	1	\$ x 580.00
12	Rear RH chassis wooden member fasteners	1	\$ x 1,600.00
13	Rear LH chassis wooden member	1set	\$ x 220.00
14	Rear LH chassis wooden member fasteners	1	\$ x 1,600.00
15	Rear platform wooden members	1set	\$ x 220.00
16	Rear step bracket	3 8	\$ Cur 440.00
17	Wooden front gate	1	\$ x 1,400.00
18	Wooden front gate frame	1	\$ x 2,200.00
19	Wooden front gate guard	1	\$ x 1,850.00
20	RH side wooden gate	1	\$ x 1,850.00
21	RH side wooden gate frame	1	\$ Cur 2,800.00
		1	\$ x 2,200.00
Total:			\$ 24,226.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 900 3,200.00
2	Spray painting on affected areas and panels	\$ 700 1,800.00
3	Check wiring and lighting system on affected areas	\$ 30 100.00
4	Apply rust coating chemical on affected areas and panels	\$ X 180.00
5	Lift up wooden platform to assist repair and replace parts	\$ 200 1,200.00
6	Lift up rear canopy assy to assist repair	\$ 200 750.00

Agreed Amount: _____ (Part by Part / Lump sum)
Working days: _____

Total: \$ 4,030.00

Spare Parts: \$ 1,630.50
Special Nett: \$ 24,226.00
Labour: \$ 4,030.00

Total Amount: \$ 29,886.50

Tanpin 97495749

WP' 31/5/23 & 220

c/b resurvey after repair

Tanpin C/Manito.com

- To check consistency of accident
- To check part prices

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	000D
Vehicle Details	
Vehicle No.:	YP7529R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 May 2023
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER4SDEB
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	4P10C75328
Chassis No.:	FEB21EA21601
Maximum Power Output:	-
Open Market Value:	\$35,494.00
Original Registration Date:	26 Oct 2017
First Registration Date:	26 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$1,775.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Oct 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,004.00
COE Rebate Amount:	\$18,484.00
Total Rebate Amount:	\$18,484.00

The information contained herein is correct as at 30 May 2023

OK