



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2303695

64 CECIL STREET  
#05-02 IOB BUILDING  
SINGAPORE 049711

INV Date 12/06/2023  
Reference CS3/GRB23005548/Kvy3m4  
Code GRB

### PROFESSIONAL SERVICE FEE

Vehicle No. SKT 3250P

Insured Veh. SLS 8846G

Claim No.

Policy No. D21MFL0000447\_02

Accident Date 27/05/2023

Inspection Date 07/06/2023

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 07.06.2023 11.11am	
- Dismantle Inspection 08.06.2023 12.29pm	
- After Repair Inspection 09.06.2023 12.57pm	
Merimen Fee	11.00
<b>Subtotal</b>	<b>131.00</b>
<b>GST (8%)</b>	<b>10.48</b>
<b>Grand Total</b>	<b>141.48</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**SML**