

SMRT Accident Vehicle Repair Estimates

SMRT Auton
60 Woodland
FAX Number
Estimator Tel
Accident Rep

Date Genera
User ID

Section A - Accident Details

Registration Number	SHB922J
Case Reference Number	TAX/05/23/2090
Registration Date	12/12/17
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	NG PENG NAM
Type of Accident	Head To Side
Accident Date and Time	30/5/23 8:50 PM
Accident Reported Date and Time	31/5/23 12:10 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118560
Special Instruction to ARC, if any	HEAD TO SIDE - PLEASE CHECK RIGHT HAND PASSENGER SEAT AREA AND RIMS/TYRE AREA
Prepared Date and Time	31/5/23 2:27 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,352.00	\$0.00
Total Spray Cost	\$1,574.00	\$0.00
Total Spare Part Cost	\$6,687.79	\$0.00
Total Other Cost	\$1,606.88	\$0.00
TOTAL COST	\$11,220.67	\$0.00
Lump Sum Total	\$11,200.00	\$0.00
Number of Repair Days	10.0	5 days
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	31/05/2023 2:49 PM	
Signature		

Not Authorized
6/1/23

Remarks

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMRT Accident Vehicle Repair Estimates

SMRT Auton
80 Woodland
FAX Number
Estimator Tel
Accident Rep

Date Genera

User ID

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicabl
TO REPAIR REAR PORTION RH	\$1,352.00 <i>700</i>	
Total Labour	\$1,352.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TO RESPRAY REAR BUMPER	\$378.00 <i>7</i>	
TO RESPRAY RIM	\$220.00 <i>60/-</i>	
TO RESPRAY REAR FENDER RH	\$378.00 <i>200/-</i>	
TO RESPRAY RH REAR DOOR	\$378.00 <i>200/-</i>	
TO RESPRAY ROCKER PANEL MOULDING	\$220.00 <i>nn X</i>	
Total Spray Painting & Panel Beating	\$1,574.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicabl
TO WASH AND VACUUM	\$60.00 <i>nn X</i>	
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00 <i>20/-</i>	
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00 <i>30/-</i>	
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00 <i>60/-</i>	
TO REMOVE AND REFIT TYRE	\$120.00 <i>nn X</i>	
TO TRANSFER DOOR MECHANISM	\$120.00 <i>nn X</i>	
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00 <i>nn X</i>	
TO REMOVE AND REFIX UNDERCARRIAGE	\$350.00 <i>7</i>	
TO REPLACE SUNDRY PARTS	\$100.00 <i>nn X</i>	
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER (NET)	\$296.88 <i>✓</i>	
Total Other Costs	\$1,606.88	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.17	Replace <i>R</i>	<i>X</i>
		5246247030	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.30	25.00	\$6.45	Replace <i>nn</i>	<i>X</i>
		5246247020	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.30	25.00	\$6.45	Replace <i>nn</i>	<i>X</i>
		5246247010	PAD, RR BUMPER, RH & LH, 3	2.00	\$4.30	25.00	\$6.45	Replace <i>nn</i>	<i>X</i>
		5246147010	PAD, RR BUMPER, CTR	3.00	\$2.50	25.00	\$5.63	Replace <i>nn</i>	<i>X</i>
		5257547040	RETAINER, RR BUMPER, RH	1.00	\$127.40	25.00	\$95.55	Replace <i>nn</i>	<i>X</i>
		5259147050	SEAL, RR BUMPER, RH	1.00	\$95.50	25.00	\$71.63	Replace <i>nn</i>	<i>X</i>
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace <i>nn</i>	<i>X</i>
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$623.50	25.00	\$467.63	Replace <i>nn</i>	<i>X</i>
		5256547900	FILLER, RR BUMPER, RH	1.00	\$168.60	25.00	\$126.45	Replace <i>nn</i>	<i>X</i>
		8155147281	LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$489.00	10.00	\$440.10	Replace <i>nn</i>	<i>X</i>
		8158147010	LENS & BODY ASSY, RR BUMPER, RH	1.00	\$544.40	10.00	\$489.96	Replace <i>nn</i>	<i>X</i>
		5839847050	COVER, REAR FLOOR UNDER, RH	1.00	\$189.20	25.00	\$141.90	Replace <i>nn</i>	<i>X</i>

[illegible]