

AUTOMOBILE HUB

VEHICLE DETAILS

VEHICLE NO : GBK4386D 2020 JULY
 VEHICLE MODEL : TOYOTA HIACE
 CHASSIS NO : JTFHT02P609990112

TP Lun Pac
Xiao Chen

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BODY PANEL <i>Agis</i>	1	\$ 1,875.50	\$ 1,875.50
2	TAILLAMP <i>New</i>	1	\$ 379.60	\$ 379.60
4	SLIDING DOOR <i>Agis</i>	1	\$ 1,611.90	\$ 1,611.90
5	FRONT DOOR WING MIRROR <i>Dmg</i>	1	\$ 450.60	\$ 450.60

TOTAL PRICE: \$ 4,317.60
 LESS 25% \$ 1,079.40
 SUB TOTAL PRICE: \$ 3,238.20

450.60
3379.5

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BODY PANEL SEALANT <i>New</i>	1	\$ 60.00	\$ 60.00
2	FRONT DOOR COMPANY ADDRESS STICKER <i>New</i>	1	\$ 30.00	\$ 30.00
TOTAL :				\$ 90.00

30

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,000.00	<i>200</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	<i>600</i>	
3	WIRING CHECK	\$ 50.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>60</i>	
5	TO TRANSFER SLIDING DOOR FITTINGS	\$ 150.00	<i>X</i>	
TOTAL:		\$ 2,350.00		

890

ESTIMATE REPORT

TOTAL PARTS COST: \$ 3,328.20
 TOTAL LABOUR COST: \$ 2,350.00
 TOTAL REPAIR COST: \$ 5,678.20

Tel: 1257-85

4/5: 11c

03 Days

APPROVED DETAILS

SURVEYOR:

CONTACT:

PART BY PART / LUMP SUM:
 NO. OF DAYS:

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

FAX:

Acknowledged by Repairer

Signature:

Date: