



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2303610

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 08/06/2023
Reference CS3/GRB23005572/Tqy3m4
Code GRB

PROFESSIONAL SERVICE FEE

Vehicle No. SJP 5385D

Insured Veh. SLP 4338Z

Claim No.

Policy No. D21MFL0000447_02

Accident Date 29/05/2023

Inspection Date 01/06/2023

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 01.06.2023 03.00pm	
- Dismantle Inspection 01.06.2023 05.08pm	
Merimen Fee	11.00
Subtotal	131.00
GST (8%)	10.48
Grand Total	141.48

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

SML