



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23005584/Uny3m4 Date: 12/06/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XE 5694D	Veh. Inspected	SJY 7623G
Policy No.	D22099811	Coverage (\$)	0.00
Claim No.	D23001906MFVT	Excess (\$)	0.00
Assign From	AINI BINTE	Assign Date	01/06/2023
2. Vehicle Particulars & Condition			
Make & Model	AUDI Q5 (A)	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WAUZZZ8R5AA040216	Colour	GREY
Odometer	101988 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/50 R19	MICHELIN	6 mm
L/H Front Tyre	235/50 R19	MICHELIN	6 mm
R/H Rear Tyre	235/50 R19	MICHELIN	6 mm
L/H Rear Tyre	235/50 R19	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	29/05/2023	Inspection Date	05/06/2023
Survey held at	NPH AUTO SERVICE BLK 9005 TAMPINES STREET 93 #01-246/254 SINGAPORE 528839		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	