

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAL	INSURANCE (S) PL		Ref:	CS3/AGI23005590/y3	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE		Date:	01/06/2023	
				Code:	AGI	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SJP 8394H	Veh. Inspected		SLR 418S	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10022618/SR	Excess (\$)		0.00	
	Assign From	LEONG ENG MING	Assign Date		01/06/2023	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.		Information				
	Accident Date	31/05/2023	Inspection Dat	е	05/06/2023	
	Survey held at	ENG SOON PAINTING SVC				
		BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969				
5a.	5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					