

Huey Yon (LKKAuto)

From: Simon Ho (LKKAuto)
Sent: Tuesday, 6 June 2023 3:53 PM
To: Huey Yon (LKKAuto)
Subject: Re: MSG-OD/ SML 682P -SURVEY BY Rasul-(CS4/MSG23005607/Rny3)

Dear Huey Yon,

Audit check done for SML682P, found not economical to repair.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>
Sent: Tuesday, 6 June 2023 3:39 pm
To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Subject: MSG-OD/ SML 682P -SURVEY BY Rasul-(CS4/MSG23005607/Rny3)

Dear Simon,

For your audit

Best Regards,

Huey Yon | case handler

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Fax: 62564315 email: hueyyon@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 408933