Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd

20 McCallum Street #09-01 Tokio Marine Centre

Singapore 069046

Tan Wan Cong

Attn:

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Date: 06 Jul 2023

Preliminary Advice

Insured Vehicle No : SMK3633S

TP Vehicle No : SHA2552K Accident Date : 26/05/2023 Make : HYUNDAI AE IONIQ HEV FL Assignment Date : 05/06/2023

Date of Inspection : 05/06/2023 Est. Duration of Repair : 3

Inspection At : COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

59 LOYANG DRIVE SINGAPORE 508969

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,451.48
Revised Amount	:S\$	5,618.28
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,618.28
Lump Sum Repair	:S\$	4,500.00

Total Loss Consideration

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have
		your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.