

(06/11/13) wef

ASS. REC. BY: John

REF:

CCY/AIS 23005631/Rpa3

161K

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNC 3279Lat Workshop my car consultants p/c
6,3W Lamhurst St OS-21

Insured:

A18

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

153K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 98K

Veh No:

SNC 3279L

Yr Regn: 2021 / OCT

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA COROLLA ALT B.H. ELE c.c 1798

Colour:

GREEN

A/C: Insured / Std / NI / NA

Speeding:

106839

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MRB2386800008476

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/452R7

R:

21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

SA/LUN

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

03/06/23

D.O.I.

06/06/23

Survey held at

my car

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

) \$ + RS \$ SI

) Photos

) Others

TOTAL

MY CAR CONSULTANT PTE LTD
(Co Reg. No. 201605878Z)
60 JALAN LAM HUAT, CARROS CENTRE
#05-68 (S737869)
Tel: 93911482

TO	: ALLAINZ	DATE	: 6-Jun-23
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
		VEHICLE DETAILS	
	:	VEHICLE NO	: SNC3279L
	:	MODEL	: TOYOTA ALTIS

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BONNET <i>bt</i> ✓	1	\$ 1,025.00	\$ 1,025.00
2	BONNET LOWER LOCK <i>bt</i> ✓	1	\$ 321.00	\$ 321.00
3	BONNET WEATHERSTRIP <i>m</i> ✓	1	\$ 68.00	\$ 68.00
4	BONNET INSULATOR <i>de</i> ✓	1	\$ 312.00	\$ 312.00
5	BONNET HINGES <i>?</i>	1	\$ 72.00	\$ 72.00
6	BONNET ABSORBER <i>X</i>	2	\$ 259.00	\$ 518.00
7	FRONT BUMPER <i>form</i> ✓	1	\$ 821.00	\$ 821.00
8	FRONT BUMPER LOWER GRILLE <i>cm</i> ✓	1	\$ 298.00	\$ 298.00
9	FRONT BUMPER SPONGE <i>cut</i> ✓	1	\$ 211.00	\$ 211.00
10	FRONT BUMPER UNDER COVER <i>X</i>	1	\$ 322.00	\$ 322.00
11	FRONT BUMPER REINFORCEMENT <i>X</i>	1	\$ 512.00	\$ 512.00
12	FRONT BUMPER SIDE RETAINER <i>m</i> ✓	2	\$ 98.00	\$ 196.00
13	FRONT BUMPER SIDE GARNISH <i>cm</i> ✓	1	\$ 159.00	\$ 318.00
14	FRONT GRILLE TOP RUBBER <i>m</i> ✓	1	\$ 82.00	\$ 82.00
15	FRONT GRILLE TOP GARNISH <i>cm</i> <i>X</i>	1	\$ 298.00	\$ 298.00
16	FRONT GRILLE <i>cm</i> ✓	1	\$ 698.00	\$ 698.00
17	FRONT GRILLE LOGO C/W SENSOR <i>cm</i> ✓	1	\$ 1,259.00	\$ 1,259.00
18	FRONT BUMPER LOWER GRILLE <i>X</i>	1	\$ 258.00	\$ 258.00
19	FRONT BUMPER LOWER COVER GARNISH RH <i>X</i>	1	\$ 212.00	\$ 212.00
20	FRONT BUMPER LOWER COVER GARNISH <i>X</i>	1	\$ 389.00	\$ 389.00
21	FRONT BUMPER FOG LAMP COVER <i>X</i>	2	\$ 130.00	\$ 260.00
22	FRONT WIPER GARNISH <i>X</i>	1	\$ 321.00	\$ 321.00
23	FRONT WIPER WASHER TANK <i>?</i>	1	\$ 359.00	\$ 359.00
24	FRONT SUPPORT PANEL <i>bt</i> ✓	1	\$ 2,124.00	\$ 2,124.00

25	FRONT FENDER <i>repuir</i>	2	\$ 658.00	\$ 1,316.00
26	FRONT FENDER INNER PANEL <i>repuir</i>	2	\$ 588.80	\$ 1,177.60
27	FRONT FENDER INNER SHIELD <i>X</i>	2	\$ 198.00	\$ 396.00
28	FRONT FENDER EMBLEM 'HYBRID' <i>m /</i>	2	\$ 52.00	\$ 104.00
29	FRONT FENDER SIDE TOP GARNISH <i>X</i>	2	\$ 159.00	\$ 318.00
30	AIRCON CONDENSOR <i>bt /</i>	1	\$ 1,568.00	\$ 1,568.00
31	AIRCON CONDENSOR DISCHARGE PIPE <i>?</i>	1	\$ 352.00	\$ 352.00
32	AIRCON CONDENSOR SUCTION PIPE <i>?</i>	1	\$ 341.00	\$ 341.00
33	AIRCON CONDENSOR AIR ARCH <i>?</i>	2	\$ 110.00	\$ 220.00
34	AIRCON COMPRESSOR <i>X</i>	1	\$ 1,550.00	\$ 1,550.00
35	FRONT BRACE PANEL <i>bt /</i>	1	\$ 342.00	\$ 342.00
36	HORN <i>X</i>	2	\$ 159.00	\$ 318.00
37	AIR CLEANER HOUSING <i>cm /</i>	1	\$ 498.00	\$ 498.00
38	AIR CLEANER AIR DUCK <i>X</i>	1	\$ 251.00	\$ 251.00
39	AIR DUCT EXTENSION <i>X</i>	1	\$ 212.00	\$ 212.00
40	ALTERNATOR <i>X</i>	1	\$ 1,587.00	\$ 1,587.00
41	FUSE BOX LH <i>X</i>	1	\$ 1,025.00	\$ 1,025.00
42	FUSE RELAY BOX RH <i>X</i>	1	\$ 798.00	\$ 798.00
43	BATTERY TRAY <i>?</i>	1	\$ 312.00	\$ 312.00
44	BATTERY TOP COVER <i>ant /</i>	1	\$ 198.00	\$ 198.00
45	BATTERY TERMINAL WIRE (POSITIVE) <i>X</i>	1	\$ 351.00	\$ 351.00
46	BATTERY TERMINAL WIRE (NEGATIVE) <i>X</i>	1	\$ 201.00	\$ 201.00
47	HYBRID BATTERY <i>ext X</i>	1	\$ 8,500.00	\$ 8,500.00
48	HYBRID BATTERY SOCKET COVER <i>?</i>	1	\$ 159.00	\$ 159.00
49	STARTER MOTOR <i>X</i>	1	\$ 1,487.00	\$ 1,487.00
50	ECU UNIT <i>X</i>	1	\$ 2,587.00	\$ 2,587.00
51	EXHAUST INTAKE MANIFOLD	1	\$ 1,211.00	\$ 1,211.00
52	ENGINE TOP COVER	1	\$ 351.00	\$ 351.00
53	RADIATOR <i>bt /</i>	1	\$ 1,780.00	\$ 1,780.00
54	RADIATOR TOP GARNISH <i>cm /</i>	1	\$ 154.00	\$ 154.00
55	RADIATOR TOP BRACKET <i>m /</i>	2	\$ 98.00	\$ 196.00
56	RADIATOR MOUNTING <i>X</i>	4	\$ 25.00	\$ 100.00
57	RADIATOR FAN COWLING <i>?</i>	1	\$ 352.00	\$ 352.00
58	RADIATOR FAN MOTOR <i>?</i>	1	\$ 364.00	\$ 364.00
59	RADIATOR FAN BLADE <i>?</i>	1	\$ 180.00	\$ 180.00
60	RADIATOR HOSE <i>?</i>	1	\$ 85.00	\$ 85.00
61	RADIATOR TOP HOSE JOINT (T) <i>?</i>	1	\$ 112.00	\$ 112.00
62	RADIATOR LOWER HOSE <i>?</i>	1	\$ 125.00	\$ 125.00

63	RADIATOR COOLANT RESERVOIR X	1	\$ 269.00	\$ 269.00
64	FRONT WIRE HARNESS ?	1	\$ 1,458.50	\$ 1,458.50
65	HEADLAMP bro ✓	2	\$ 1,985.00	\$ 3,970.00
66	HEADLAMP CHROME MOULDING X	2	\$ 125.00	\$ 250.00
67	HEADLAMP TOP PANEL bt ✓	2	\$ 215.00	\$ 430.00
68	HEAD LAMP LOWER BRACKET ?	4	\$ 58.00	\$ 232.00
69	REAR BUMPER torn -	1	\$ 798.00	\$ 798.00
70	REAR BUMPER LOWER X	1	\$ 570.00	\$ 570.00
71	REAR BUMPER SENSOR re ✓	2	\$ 389.10	\$ 778.20 5/12/20
72	REAR BUMPER REFLECTOR LH cm ✓	1	\$ 85.00	\$ 85.00
73	REAR BUMPER CHROME GARNISH X	1	\$ 298.00	\$ 298.00
74	REAR BUMPER RETAINER re ✓	2	\$ 105.00	\$ 210.00
75	REAR BUMPER REINFORCEMENT bt ✓	1	\$ 397.00	\$ 397.00
76	REAR BUMPER REINFORCEMENT BRACKET bt ✓ 1/2	1	\$ 112.00	\$ 224.00
77	AIR VENT X	1	\$ 65.80	\$ 65.80
78	BOOTLID bt ✓	1	\$ 1,258.00	\$ 1,258.00
79	BOOTLID INNER TRIM X	1	\$ 321.00	\$ 321.00
80	BOOTLID REFLECTOR X	2	\$ 489.00	\$ 978.00
82	BOOT LID HINGE X	2	\$ 259.00	\$ 518.00
83	BOOTLID TOP LOCK ?	1	\$ 398.00	\$ 398.00
84	BOOTLID OUTER CHROME MOULDING X	1	\$ 357.00	\$ 357.00
85	BOOTLID LOWER LOCK X	1	\$ 40.00	\$ 40.00
86	BOOTLID WEATHERSTRIP re ✓	1	\$ 220.00	\$ 220.00
87	BOOTLID LOGO re ✓	1	\$ 75.00	\$ 75.00
88	BOOTLID EMBLEM 'COROLLA' re ✓	1	\$ 65.00	\$ 65.00
89	BOOTLID EMBLEM 'ALTIS' re ✓	1	\$ 75.00	\$ 75.00
90	BOOTLID EMBLEM 'HYBRID' re ✓	1	\$ 72.00	\$ 72.00
91	BOOTLID SENSOR X	1	\$ 312.00	\$ 312.00
92	TAILLAMP LH - cm ✓	1/2	\$ 798.00	\$ 1,596.00
93	REAR FENDER LH - repair	1/2	\$ 1,024.00	\$ 2,048.00
94	REAR FENDER INNER COWLING X	2	\$ 358.00	\$ 716.00
95	REAR FENDER INNER TRIM ? LH-?,	1/2	\$ 770.00	\$ 1,540.00
96	REAR END PANEL bt ✓	1	\$ 695.00	\$ 695.00
97	REAR END PANEL TOP GARNISH cm ✓	1	\$ 280.00	\$ 280.00
98	REAR FLOOR PANEL bro ✓	1	\$ 1,025.00	\$ 1,025.00
99	REAR FLOOR PANEL TOP BOARD X	1	\$ 357.00	\$ 357.00
100	REAR FLOOR PANEL TOP SPONGE X	1	\$ 358.00	\$ 358.00
101	REAR FLOOR SIDE PANEL LH-?	2	\$ 359.00	\$ 718.00

102	REAR EXHAUST HEAT SHIELD <i>X</i>	1	\$ 360.00	\$ 360.00
-----	-----------------------------------	---	-----------	-----------

TOTAL PRICE \$ 64,534.10
 LESS 25% \$ 16,133.53
 SUB TOTAL PRICE \$ 48,400.58

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>bt</i>	1	\$ 50.00	\$ 50.00 <i>35</i>
2	FRONT BUMPER CLIPS <i>m/</i>	10	\$ 6.50	\$ 65.00 <i>30</i>
3	FRONT BUMPER LOWER GRILLE CLIP <i>m/</i>	8	\$ 6.50	\$ 52.00 <i>30</i>
4	FRONT BUMPER LOWER COVER GARNISH CLIP RH <i>2</i>	6	\$ 6.50	\$ 39.00 <i>} 50</i>
5	FRONT BUMPER LOWER COVER GARNISH CLIP LH <i>2</i>	6	\$ 6.50	\$ 39.00 <i>} 50</i>
6	FRONT RADIATOR GRILLE CLIP <i>m/</i>	4	\$ 6.50	\$ 26.00 <i>20</i>
7	FRONT SUPPORT SEALANT <i>X</i>	1	\$ 80.00	\$ 80.00 <i>X</i>
8	REAR NUMBER PLATE <i>X</i>	1	\$ 50.00	\$ 50.00 <i>X</i>
9	REAR BUMPER CLIPS <i>m/</i>	10	\$ 6.50	\$ 65.00 <i>30</i>
10	RADIATOR COOLANT <i>m/</i>	1	\$ 50.00	\$ 50.00 <i>✓</i>
11	BATTERY <i>at/</i>	1	\$ 300.00	\$ 300.00 <i>150</i>
12	BOOT LID INSULATOR CLIP <i>m/</i>	10	\$ 6.50	\$ 65.00 <i>40</i>
13	BOOTLID STICKER <i>m/</i>	1	\$ 100.00	\$ 100.00 <i>60</i>
14	TAILAMP CLIPS <i>m/</i>	4	\$ 8.00	\$ 32.00 <i>10</i>
15	REVERSE CAMERA <i>X</i>	1	\$ 450.00	\$ 450.00 <i>X</i>
16	REAR FENDER SEALANT <i>X</i>	2	\$ 150.00	\$ 300.00 <i>X</i>
17	REAR FENDER COWLING CLIPS <i>X</i>	12	\$ 6.50	\$ 78.00 <i>X</i>
18	REAR FENDER INNER TRIMD CLIPS <i>X</i>	12	\$ 6.50	\$ 78.00 <i>X</i>
19	REAR END PANEL TOP GARNISH CLIPS <i>m/</i>	6	\$ 6.50	\$ 39.00 <i>30</i>
20	REAR END PANEL INSULATION SEAL <i>X</i>	1	\$ 150.00	\$ 150.00 <i>X</i>
21	REAR FLOOR PANEL SEALANT <i>m/</i>	1	\$ 120.00	\$ 120.00 <i>60</i>

TOTAL \$ 2,228.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$1,600.00	<i>900</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$1,400.00	<i>1000</i>	
3	WIRING CHECK	\$200.00	<i>60</i>	
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$150.00	<i>120</i>	

5	REMOVE AND REFIX HYBRID BATTERY AND ERESET CODE	\$500.00	X	
6	RESET ENGINE TROUBLE CODE	\$300.00	X	
7	RADIATOR PRESSURE TEST	\$120.00	60	
8	REFOCUS HEADLAMP BEAM	\$60.00	30	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$1,600.00	1000	
2	TO SPRAY PAINT AFFECTED AREA	\$1,400.00	1000	
3	TUFF COAT	\$250.00	60	
4	WIRING CHECK	\$80.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$300.00	60	
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$80.00	40	
9	REAR CHASSIS ALIGNMENT LH	\$400.00	200	
10	TRANSFER BOOTLID MECHANISM	\$60.00	40	
11	CONDUCT WATER LEAKAGE TEST	\$100.00	30	

TOTAL

\$8,600.00

TOTAL PARTS COST : \$ 50,628.58
TOTAL LABOUR COST : \$ 8,600.00
TOTAL REPAIR COST : \$ 59,228.58

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Panel
Hp 90010068
17 days
L/S
06/06/23 @ 1600
Recy after repair

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	961K
No.:	SNC3279L
to be Exported:	No
d Deregistration Date:	08 Jun 2023
Make:	TOYOTA
Model:	COROLLA ALTIS HYBRID ELEGANCE(AUTO)(2WD)
Colour:	Grey
cturing Year:	2021
No.:	2ZRY780687
No.:	MR2BZ3BE800008476
im Power Output:	90.0 kW (120 bhp)
arket Value:	\$26,491.00
Registration Date:	13 Oct 2021
egistration Date:	13 Oct 2021
Transfer Count:	0
Actual ARF Paid:	\$14,088.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Oct 2031
PARF Rebate Amount:	\$10,566.00
COE Expiry Date:	12 Oct 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,309.00
COE Rebate Amount:	\$43,647.00
Total Rebate Amount:	\$54,213.00

The information contained herein is correct as at 08 Jun 2023

OK

Toyota Corolla Altis Hybrid 1.8A Elegance

\$143,330 Instalment \$1,237/mth

♡ Shortlist

📅 Loan Calculator



Overview Financial Photo Research

Depreciation	ⓘ \$17,250 / year
Reg. Date	18-Mar-2021 (7yrs 9mths 9days COE left)
Manufactured	ⓘ 2020
Mileage	43,167 km (19.4k / year)
Transmission	Auto
Engine Cap	1,798 cc
Power	90.0 kW (120 bhp)
Curb Weight	ⓘ 1,410 kg
Fuel Type	Petrol-Electric
COE	ⓘ \$45,001
OMV	ⓘ \$29,487
ARF	ⓘ \$18,282
Dereg Value	ⓘ \$48,714 as of today
No. of Owners	ⓘ 1